

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1709 Ben Lomond Dr.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1709 Ben Lomond Dr. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-003-003

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1928. It is rectangular in plan with flat roof to rear, pitched roof at front elevation and projecting first story wing with front gable roof all clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are fixed and casement arched rectangular divided-lights constructed of wood; the door is recessed. Character-defining features include a projecting balcony with wood posts and balustrade, exposed rafter tails, arched fixed picture window, stepped corbels under roofline, and arched corbels under overhanging second story. Landscaping consists of lawn, brick walkway and stairs leading to main entrance, and palm trees. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1928
City of Glendale Building Permit Records

*P7. Owner and Address:
RAYMOND F & MARY J RECENDEZ
1709 BEN LOMOND DR
GLENDALE CA 91202-1005

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 3/30/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1714 Ben Lomond Dr.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1714 Ben Lomond Dr. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-004-006

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the American Colonial Revival style, constructed in 1936. It is rectangular in plan with a hip roof, clad in asphalt shingles. The walls are clad in smooth stucco with accents of brick trim. The primary façade is asymmetrical. The windows are divided-light casement windows constructed of wood; the door is framed by shutters and a pediment. Character-defining features include the front gable wall dormers, second story balcony with metal balustrade, chimney, decorative fixed wood shutters flanking doors and windows on lower portion of the façade, and a roofline frieze. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
WILLIE O JR & CHRISTINE SIMMONS
1714 BEN LOMOND DR
GLENDALE CA 91202-1006

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1715 Ben Lomond Dr.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T ____ ; R ____ ; 1/4 of ____ 1/4 of Sec ____ ; ____ B.M.

c. Address 1715 Ben Lomond Dr. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone ____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-017

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-and-a-half-story single-family residence designed in the English Tudor Revival style, constructed in 1926. It is rectangular in plan with a steeply-pitched cross-gable roof, clad in asphalt shingles. The walls are clad in smooth stucco with brick accents. The primary façade is asymmetrical. The windows are divided-light casement and one projecting three-sided by window constructed of wood; the door is wood. Character-defining features include a chimney, gabled roof dormers, exposed rafter tails, and arched opening front gable with brick door surround. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
Los Angeles County Assessor

*P7. Owner and Address:
MATTHEW K MANNER
1715 BEN LOMOND DR
GLENDALE CA 91202-1005

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
3/30/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1719 Ben Lomond Dr.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1719 Ben Lomond Dr. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-016

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style with some Ranch influence, constructed in 1949. It is rectangular in plan with a two front gables and a side-gable roof, clad in asphalt shingles. The walls are clad in brick on the primary façade with wood-lap in gable ends. The primary façade is asymmetrical. The windows are fixed and casement and projecting three-sided bay with diamond-panes constructed of steel. Character-defining features include decorative brickwork, half-timbering on gable end at side elevation, brick chimney, wrought iron railings, and three-sided bay window with metal roof. Landscaping consists of lawn and mature trees and bushes. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1949
City of Glendale Building Permit Records

*P7. Owner and Address:
ELROD CALVIN R CO TR
1719 BEN LOMOND DR
GLENDALE CA 91202-1005

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 3/30/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1720 Ben Lomond Dr.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1720 Ben Lomond Dr. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-004-007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style with Tudor Revival influence, constructed in 1950. It is L-shaped in plan with a cross-gable roof, clad in asphalt shingles. The walls are clad in smooth stucco with wood lap in the gable end. The primary façade is asymmetrical. The front porch is covered with a front gable roof, exposed truss and supported by wood posts with diagonal braces. The windows are fixed divided-light with leaded diamond panes constructed of metal. Character-defining features include two bay windows, and half timbering. Alterations include a modified porch in 1991 and a contemporary door. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1950
City of Glendale Building Permit Records

*P7. Owner and Address:
LEE A & CAROL M JOHNSON TR
1720 BEN LOMOND DR
GLENDALE CA 91202-1006

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1724 Ben Lomond Dr.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1724 Ben Lomond Dr. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-004-008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1928. It is L-shaped in plan with cross-gable roof with two front facing gables, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are casement divided-lights constructed of wood. Character-defining features include an exterior courtyard enclosed with low stucco wall, projecting and inset balcony with wood posts and balustrade, a chimney, and a tile walkway. Alterations include the addition of canvas awning. Landscaping consists of lawn, various plantings, and large mature trees the partially obscures view of residence. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1928
City of Glendale Building Permit Records

*P7. Owner and Address:
JOHN F & CAROLANNE R RAPISARDI
1724 BEN LOMOND DR
GLENDALE CA 91202-1006

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1725 Ben Lomond Dr.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T ___ ; R ___ ; 1/4 of ___ 1/4 of Sec ___ ; B.M.

c. Address 1725 Ben Lomond Dr. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone __, ___ mE/ ___ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1928. It is L-shaped in plan with a front gable on projecting one-story wing and a side-gable on the second floor, clad in clay tile. The primary façade is asymmetrical. The windows are fixed and casement divided-light constructed of wood. A large pointed arch picture window adorns the projecting one-story wing. Character-defining features include an enclosed courtyard with low stucco wall, projecting second story balcony with wood balustrade, decorative tiles, a rounded tower with clay tile roof, and wing wall with pointed arch opening to courtyard. Landscaping consists of large trees and hedges lining the walkway. Alterations include rough-troweled stucco replacing the original smooth stucco cladding. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1928
City of Glendale Building Permit Records

*P7. Owner and Address:
COLIN P & CANDICE TOM
1725 BEN LOMOND DR
GLENDALE CA 91202-1005

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 3/30/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1729 Ben Lomond Dr.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1729 Ben Lomond Dr. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-014

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one and a half story single-family residence designed in the English Tudor Revival style, constructed in 1926. It is rectangular in plan with steeply-pitched side-gable roof with three front facing gables, some clipped, clad in concrete tile. The walls are clad in smooth stucco with accents of half-timbering. The primary façade is asymmetrical. The windows are double-hung, casement and fixed divided-light and include large fixed picture window and inset three-sided bay window with wood casement and transom above, constructed primarily of wood; the door is deeply recessed. Character-defining features include arched openings, wood shutters, half-timbering, decorative brickwork around front archway, and a Porte Cochere over the driveway. Alterations include a room addition on the second story permitted in 1983; not visible from the public right-of-way. Landscaping consists of a large pine tree in front of house. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
City of Glendale Building Permit Records

*P7. Owner and Address:
JONATHAN & KATHERINE ACKLEY
1729 BEN LOMOND DR
GLENDALE CA 91202-1005

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 3/30/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1733 Ben Lomond Dr.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1733 Ben Lomond Dr. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed with elements of Minimal Traditional and Ranch styles, constructed in 1947. It is rectangular in plan with a gable-on-hip roof, clad in asphalt shingles. The walls are clad in smooth stucco with stone veneer and wood-lap on primary façade. The primary façade is asymmetrical. The windows are double-hung, divided-light, and projecting three-sided bay window constructed of wood. Character-defining features include wood shutters, inset porch, and a trio of vertical wooden slats that serve as porch supports with a gentle arched header. The house has a wrapped around orientation consistent with its placement on a corner lot. Alterations include enclosure of patio and addition at rear of residence in 1959. Landscaping consists of a lawn, various plantings, concrete walkway and mature tree. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1947
City of Glendale Building Permit Records

*P7. Owner and Address:
STEVEN R & MARY S TATHAM
1733 BEN LOMOND DR
GLENDALE CA 91202-1005

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
3/30/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1645 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 1645 Cleveland Rd. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
 Los Angeles County Assessor's Parcel Number: 5629-008-010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Ranch style, constructed in 1962. It is rectangular in plan with a low-pitched gable roof with broad eaves, clad in wood shingles. The walls are clad with rough stucco with vertical board wood accents. The façade is asymmetrical. The windows are sliding with aluminum framing. The main entry is recessed within an entry portico with two concrete steps to landing. The non-original front door features sidelights. Character-defining features are low-pitched roof, central chimney faced with irregular cut stone and a second chimney constructed of brick and attached two-stall garage. The building appears to be unaltered. Landscaping consists of side driveway of concrete, sloping lawn with central concrete pathway to door, various plants and young palm trees. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1962
Los Angeles County Assessor

*P7. Owner and Address:
GRIGOR & ARAKSYA TOROSIAN
1645 CLEVELAND RD
GLENDALE CA 91202-1009

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 4/21/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1714 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1714 Cleveland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-002-006


*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the French Eclectic style, constructed in 1926. It is irregular in plan with a multiple gabled roof, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are primarily vinyl; the entryway is situated between two protruding front wings. Character-defining features include a left front gable distinguished by a large picture window with tripartite narrow top lights and small mullions, dormer windows, a prominent chimney attached to the side of house, masonry stairs leading up to the main entryway, and an exterior courtyard. Alterations include a minor addition to the right side of house in 1989, the removal of right front gable diamond-pane windows, replacement of wood windows at side façade with vinyl, and replacement of masonry stairs with cement brick. Landscaping consists of a dominant mature spruce in the front lawn, brick stairway and planters, and variety of shrubs and flowers. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
Los Angeles County Assessor

*P7. Owner and Address:
DAVID G PARKHURST
1714 CLEVELAND RD
GLENDALE CA 91202-1012

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1715 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1715 Cleveland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-001-023

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the English Tudor Revival style, constructed in 1926. It is rectangular in plan with multiple steeply-pitched gabled roof, clad in asphalt shingles. The walls are clad in stucco. The primary façade is asymmetrical. The windows are horizontal sliders constructed of vinyl; the primary door is placed perpendicular to the street in an entryway defined by a recessed door and gabled roof. Character-defining features are lattice work vents with pointed arch on front gables, dominant front gable with extended eaves, clay attic vents in two dormers, protruding sill and surround on windows fronting the front gables, and half height wall enclosing the front patio. Alterations include the installation of vinyl windows. Landscaping consists of a mature tree in the front lawn. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
Los Angeles County Assessor

*P7. Owner and Address:
ARUTUN & SILVA PILIKYAN
1715 CLEVELAND RD
GLENDALE CA 91202-1011

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1718 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 1718 Cleveland Rd. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
 Los Angeles County Assessor's Parcel Number: 5629-002-007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed with English Tudor Revival influences, constructed in 1926. It is rectangular in plan with a cross-gabled roof covering the central block and a dominant front gable capped with a hip, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are primarily divided-light casements constructed in wood, with a fixed window constructed in aluminum; the wood door is flanked by sidelights. An elevated brick terrace stands at the front façade. Tile walkway and front steps Character-defining features are accentuated front door with decorative pediment and slender wood columns forming an entry porch, bay window with single panes capped with a metal hood, two panels of decorative venting on the front gable, and thick stucco chimney adjacent to entry porch. Alterations include contemporary door and sidelights, removal of original enclosed porch at left side of the house, addition of porch pediment and tile walkway and steps. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
Los Angeles County Assessor

*P7. Owner and Address:
VAN D JUDE
1718 CLEVELAND RD
GLENDALE CA 91202-1012

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1719 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1719 Cleveland Rd. _____ City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-001-010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1927. It is irregular in plan with a multiple gabled roof, clad in clay tile. The walls are clad in stucco. The primary façade is asymmetrical. The windows are non-original aluminum horizontal sliders and double-hung divided-lights and fixed and casement windows constructed of wood. The wooden door is housed in a inset entry porch balanced by a recessed arched shelf. Character-defining features are entry porch defined by arcaded openings, clay tile roof and original red tile stairs, decorative venting on front gables, tripartite picture window on prominent front wing with single large central pane flanked with divided-light, sides raised stucco decoration, and wooden shutters; varied roof line due to multiple gabled wings and additions, and wooden shutters flanking all sets of windows on central block. Alterations include installation of aluminum window. Landscaping consists of a mature tree in the front lawn. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1927
City of Glendale Building Permit Records

*P7. Owner and Address:
BRENDA J BANISTER
1719 CLEVELAND RD
GLENDALE CA 91202-1011

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1723 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1723 Cleveland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1941. It is irregular in plan with a side-gable roof covering the central block and a hipped roof capping the front wing all clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are primarily double-hung accented with single diamond pane fixed windows all constructed of wood; the door is centrally located on the façade with no defining entryway. Character-defining features are projecting three-sided bay window with leaded glass and flagstone base, brick chimney located on the side of the house, and wood shutters flanking front façade windows. Alterations include contemporary style door and canvas awnings capping sets of windows on the façade. Landscaping consists of mature sycamore and flagstone pathway leading to the main entry. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1941
Los Angeles County Assessor

*P7. Owner and Address:
MARGARET M SIMPKINS
1723 CLEVELAND RD
GLENDALE CA 91202-1011

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1724 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1724 Cleveland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1935. It is L-shaped in plan with a cross-gabled roof, clad in asphalt shingles with clay tile ridge. The walls are clad in smooth stucco with accents of brick and wood. The façade is asymmetrical. The windows are primarily divided-light double-hung or fixed windows all constructed of wood. Character-defining features are exposed rafter tails at all visible roof edges, projecting bay window with brick sill, scalloped wood trim and metal crown prominently situated on the protruding wing façade, arched vents in wood trim in front gable, decorative wood window shutters on all visible double-hung windows, and a covered front porch extending into a Porte Cochere. Alterations include a replacement of the bay window with exact likeness in 1997, reroof replacing asphalt shingles with non-wood shakes, addition of small skylight on horizontal gable. Landscaping consists of lush foliage outlining the front façade. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935

City of Glendale Building Permit Records

*P7. Owner and Address:

PETER H & ZUZKA P EGGENA

1724 CLEVELAND RD

GLENDALE CA 91202-1012

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded:

5/26/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1728 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1728 Cleveland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1927. It is square in plan with a gabled roof at front elevation and flat roof with clay tile parapet to the rear. The walls are clad in smooth stucco. The primary façade is symmetrical. The windows are primarily casement with some fixed windows all constructed of wood. Character-defining features are an exterior courtyard, very broad front gabled wing with centrally placed picture window flanked by fixed side windows, low-pitched side gabled roof above the central block, and arched openings to the side courtyard. Alterations include installation of a metal awning above the prominent picture window on front façade. Landscaping consists of front lawn and a variety of mature shrubs. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1927
City of Glendale Building Permit Records

*P7. Owner and Address:
CHARLES K & AMY K ABE
1728 CLEVELAND RD
GLENDALE CA 91202-1012

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1729 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1729 Cleveland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-001-008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1927. It is square in plan with a side gabled roof, clad in clay tile. The walls are clad in rough stucco and the façade is asymmetrical. All front façade windows are vinyl. Most character-defining features have been removed, including wood fixed windows and circular vents at front façade. The remaining character-defining feature is a protruding front entranceway defined by an extension of roofline and a deeply recessed front door. Alterations include non-original vinyl windows, contemporary door, removal of ornamentation above the prominent story window, and removal of circular vents at front façade. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1927
City of Glendale Building Permit Records

*P7. Owner and Address:
RAYMOND & RIMA SINANI
1729 CLEVELAND RD
GLENDALE CA 91202-1011

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1734 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T ___ ; R ___ ; 1/4 of ___ 1/4 of Sec ___ ; B.M. ___
 c. Address 1734 Cleveland Rd. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone ___, ___ mE/ ___ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
 Los Angeles County Assessor's Parcel Number: 5629-002-010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the American Colonial Revival style, constructed in 1936. It is rectangular in plan with a hipped roof, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are double-hung and constructed of wood. Character-defining features are exposed rafter tails, stained glass windows in several frames, decorative wooden shutters framing the windows, and a porch which wraps around from the right side to the right front. Alterations include a bathroom addition in 1967, enclosure of the patio with an aluminum cover in 1969, and a second story addition in 1991. Significant landscaping consists of: a variety of semi-mature trees and a stone pathway leading from the driveway through the lawn to the front door. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
CHRISTIAN R & JANET C JUNG
1734 CLEVELAND RD
GLENDALE CA 91202-1012

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1735 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T ___ ; R ___ ; 1/4 of ___ 1/4 of Sec ___ ; B.M.

c. Address 1735 Cleveland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone __, ___ mE/ ___ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1936. It is L-shaped in plan with a cross-gabled roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are primarily divided-light casements with some fixed arched single pane windows constructed of steel. Character-defining features are a square "tower" imbedded in the ell of the L-shaped structure with hipped roof, clay pipe attic vents defining front gables and square "tower" roof lines, low wall defining exterior courtyards in front and side, wrought iron gates, doorway housed in tower with arched openings, stained glass, projecting bay window capped with clay tile, and a deeply recessed arched picture window on the front gable. Landscaping consists of a mature palm tree. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
THIMIOS & MARY GENKOS
1735 CLEVELAND RD
GLENDALE CA 91202-1011

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1800 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T ____ ; R ____ ; 1/4 of ____ 1/4 of Sec ____ ; ____ B.M.

c. Address 1800 Cleveland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone ____, ____ mE/ ____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-030

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1941. It is L-shape in plan with a side gable roof clad with asphalt shingles. The primary façade is asymmetrical. The walls are clad with horizontal wood-lap siding with accents of stucco. The windows consist of double-hung divided-lights, with fixed shutters and a projecting three-sided bay window with fixed lights and double-hung divide sidelights, all constructed of wood. The main entry consists of an inset porch with a wood door and sidelight. Character-defining features include a brick double flue chimney, a brick apron under the bay window, decorative wood shutters, and copper hood above the bay window. Alterations include contemporary garage door, bedroom addition at the rear in 1978 and master bedroom, bath and family room addition in 1998. Landscaping consists of a lawn, planter areas next to structure, bedded flowers lining the walkway, and a small curved walkway leading from driveway to front entry. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1941
City of Glendale Building Permit Records

*P7. Owner and Address:
MICHAEL J SCHWALBACH
1800 CLEVELAND RD
GLENDALE CA 91202-1014

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1808 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1808 Cleveland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-029

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family one-story residence designed in the Ranch style, constructed in 1941. It is L-shaped in plan with a cross-gable roof clad with faux wood shingles. The primary façade is asymmetrical. The walls are clad with lapped wood shingle. The windows are fixed three-sided bay, casement, and double-hung divided-light constructed of wood. The main entry is recessed with minimal brick porch and semi-elliptical cross beam and three panel door. The projecting section contains attached garage with vertical board garage door. Character-defining details include wood shingle siding, decorative wood shutters, a minimal porch and projecting bay windows. Landscaping consists of curved driveway, lawn and various plantings including cypress. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1941
Los Angeles County Assessor

*P7. Owner and Address:
THOMAS R & JOANNE MOORE
1808 CLEVELAND RD
GLENDALE CA 91202-1014

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1811 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M.

c. Address 1811 Cleveland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-038

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Mediterranean Revival style, built 1927. It is slightly L-shaped in plan with a low-pitch hip and side-gable roof clad with clay barrel tile. The eaves overhang slightly and are boxed without brackets. The primary façade is asymmetrical and the walls are clad with stucco. It exhibits a simple, slightly unadorned, presence. The windows are wood double casement divided-lights, vertical sash, and casement. The main arched entry is recessed and features an eight panel wooden door, with cast stone surround. Character-defining features include small entry with a decorative cast stone surround and decorative wrought iron rails, a small recessed arched window next to right side of entry small arched vents, molded-belt course on gabled wing, chimney, and wood shutters. Landscaping consists of lawn and planting beds against structure, and large mature trees. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1927
Los Angeles County Assessor

*P7. Owner and Address:
STEPHEN M & ELIZABETH V ASTOR
1811 CLEVELAND RD
GLENDALE CA 91202-1013

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1812 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1812 Cleveland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-005-027

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Mediterranean Revival style, built in 1921. It is rectangular in plan with a low to moderate pitch hipped roof clad with composition shingles. The primary façade is asymmetrical. The walls are clad with stucco. Windows are wood double casement vertical sashes divided-lights. The recessed entry is arched with a divided transom and French doors; large arch opens to side courtyard. Character-defining features include chimney, one-story projecting section, decorative iron work, tall and narrow casement windows, and exposed rafter tails. Alterations include the addition of a carport with hip roof and elliptical arches in 1995 and canvas awnings. Landscape consists of palm trees, ivy, lawn, and brick walkway. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1921
Los Angeles County Assessor

*P7. Owner and Address:
DENNIS & TERRY L HODGSON
1812 CLEVELAND RD
GLENDALE CA 91202-1014

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1816 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1816 Cleveland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-026

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story-single-family residence designed in the Neo-Spanish Colonial Revival style, constructed in 1990. It is L-shaped in plan with a low-pitch hip roof and shed roof over garage, clad in clay tile. The primary façade is asymmetrical. The walls are clad in smooth stucco. The windows are recessed vertical wood double and casement with divided-lights; the paneled door is constructed of wood. Character-defining features are one story garage, exposed rafter tails, decorative iron work, tall and narrow casement windows. Alterations include the addition of the front gate and wall with brick posts in 1992. Landscape consists of wide cement driveway, series of brick steps leading to main entry, lawn and planter area. The overall integrity of this building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1990

Los Angeles County Assessor

*P7. Owner and Address:

LIANNA TONAKANYAN

1816 CLEVELAND RD

GLENDALE CA 91202-1014

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

2/10/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1817 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1817 Cleveland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-039

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the English Tudor Revival style, constructed in 1926. It is rectangular in plan with a steeply-pitched hipped gable roof with front facing gable and shed roofed one-story with wood divided-light window. The roof is clad with asphalt shingles. The primary façade is asymmetrical. The walls are clad with stucco and, at the front projection, vertical wood siding. There is half-timbering in the gable ends. The windows are casement and fixed divided-lights constructed of wood. Character-defining features include chimney, decorative wood shutters, and steeply-pitched and clipped gable roof. Alterations include the addition of half-timbering in the gable ends. Landscaping consists of brick planter and retaining wall with lawn hedge clipped bushes and other low growing plants. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
City of Glendale Building Permit Records

*P7. Owner and Address:
BRAD A & CYNTHIA M BROWN
1817 CLEVELAND RD
GLENDALE CA 91202-1013

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1826 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1826 Cleveland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-014

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1937. It is L-shaped in plan with a low-pitch hip roof, clad in asphalt shingles. The primary façade is asymmetrical. The walls are clad with horizontal wood siding and smooth painted brick. The windows consist of vinyl divided-light casement windows and a vinyl three-sided bay window with fixed sashes. The garage door is of a contemporary design. Character-defining features include copper hood above the bay window, shed roof porch supported by square post with lattice detailing, and decorative wood shutters. Landscaping consists of curved cement walk way to porch with lawn and various plantings. Alterations include a contemporary garage door. The overall integrity of this building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1937
Los Angeles County Assessor

*P7. Owner and Address:
DANIEL & KARINEH BERGE
1826 CLEVELAND RD
GLENDALE CA 91202-1014

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1846 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1846 Cleveland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-018

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1932. It is L-shaped in plan with a gabled roof at the front elevation, clad in clay tile. The walls are clad in smooth stucco and wood. The primary façade is asymmetrical. The windows are fixed and sliding constructed of aluminum and vinyl. Character-defining features include an exterior courtyard, decorative wrought iron, and a Porte Cochere with arch. Alterations include non-original aluminum and vinyl windows and driveway. Landscaping features include a sloping lawn and boulders. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1932
City of Glendale Building Permit Records

*P7. Owner and Address:
PETER J KOUVELIS
1846 CLEVELAND RD
GLENDALE CA 91202-1056

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1847 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1847 Cleveland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-027

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1935. It is T-shaped in plan with a low-hipped roof, clad in asphalt shingles. The walls are clad in smooth stucco and horizontal wood. The façade is asymmetrical. The windows are divided-light casement and fixed, constructed of vinyl, as well as diamond-patterned glazing at the front bay window. Character-defining features include main entrance sheltered by inset partial-width porch with decorative wood supports. Alterations include non-original brick paved driveway and walkway. Landscaping consists of a mature American sweet gum tree. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
City of Glendale Building Permit Records

*P7. Owner and Address:
WILLIAM G BURDETTE
1847 CLEVELAND RD
GLENDALE CA 91202-1055

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1851 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1851 Cleveland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-028

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Minimal Traditional style, constructed in 1937. It is T-shaped in plan with a cross-gable roof, clad in asphalt shingles. The walls are clad in rough stucco with wood accents and a brick exterior chimney. The primary façade is asymmetrical. The windows are wood divided-light double-hung vinyl sliding. Character-defining features include a covered porch, winding brick walkway, front facing gables, and brick chimney. Alterations include the addition on the second story in 1973. Landscaping consists of a lawn, rose bushes, and various plantings. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1937
City of Glendale Building Permit Records

*P7. Owner and Address:
JEARLD W & JOSEPHINE HALL TR
641 W KENNETH RD
GLENDALE CA 91202-1451

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1854 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1854 Cleveland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-004-019

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Minimal Traditional style, constructed in 1937. It is rectangular in plan with a side-gabled roof, clad in asphalt-shingles. The walls are clad in smooth stucco on the lower story and wood-lap on the upper story. The primary façade is asymmetrical. The windows are divided-light double-hung constructed of wood. The six-paneled door is constructed of wood. Character-defining features are three gabled wall dormers, one hipped wall dormer, projecting three-sided bay window, side gables and stepped room wings. Landscaping consists of sloping lawn with stairs leading up to main entry. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1937
City of Glendale Building Permit Records

*P7. Owner and Address:
WALTER H&DOLORES M ALBRO TRUST
1854 CLEVELAND RD
GLENDALE CA 91202-1056

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1857 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1857 Cleveland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-004-031

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1940. It is square in plan with a hipped roof, clad in asphalt shingles. The walls are clad in smooth stucco and wood with brick accents. The primary façade is asymmetrical. Windows are double-hung and appear to be made of wood. Character-defining features include inset porch with wood support post. A straight walkway leads to the main entrance in the porch. The overall integrity of the building appears excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1940
City of Glendale Building Permit Records

*P7. Owner and Address:
FRANKLIN & CATHERINE DOREY TR
1857 CLEVELAND RD
GLENDALE CA 91202-1055

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1861 Cleveland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1861 Cleveland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-032

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Mediterranean Revival style, constructed in 1925. It is rectangular in plan with a low-pitch cross-gabled roof. The walls are clad in textured smooth stucco. The façade is symmetrical. The windows are single-pane, casement, arched, and divided-light, constructed primarily of wood with some metal windows. The arched door appears to be wood. Character-defining features include corbels, iron grille work, arched door and window openings on the first story, second-story balcony with paired arches and wrought iron balustrade, round clay vents in gable end. Alterations include an addition in the rear. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
City of Glendale Building Permit Records

*P7. Owner and Address:
BRETT S & ANGELA KELLY
1861 CLEVELAND RD
GLENDALE CA 91202-1055

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1000 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1000 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the French Eclectic style, constructed in 1936. It is irregular in plan with a hipped and gable roof, clad in wood shingles. The round tower main entry features a conical roof, clad in wood shingles. The walls are clad in smooth stucco with brick accents. The primary façade is asymmetrical. The windows include two diamond pane bay windows adjacent to the main entry, several divided-light casement windows, narrow vertical lights in the tower, and three bay windows on side elevation. Alterations include non-original double doors and vinyl sliding door near the main entry. Character-defining features include exterior courtyard enclosed by half height brick wall with decorative metal railing and gate, diamond pane windows, and weather vane above conical entry. Curved brick planters with fan Palms nasturtiums and other flowering ground cover are included in landscape. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
JULIUS & PAULINE HENNING TR
1000 CRESTVIEW AVE
GLENDALE CA 91202-1018

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1001 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 1001 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-020

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1938. It is irregular in plan with medium-pitched hipped roof, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. Fenestration consists of divided-light double-hung windows constructed of wood, some with non-original fixed shutters; the six-panel door is constructed of wood and features a non-original surround. Character-defining features are slightly overhanging eaves with exposed rafter tails, main entrance recessed within projecting entry porch with wood posts, brick chimney, decorative basement vents on side and front. Landscaping consists of sloped front lawn with concrete steps leading to front landing. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1938
City of Glendale Building Permit Records

*P7. Owner and Address:
SETH OVANESPOUR
1001 CRESTVIEW AVE
GLENDALE CA 91202-1017

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/19/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1008 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1008 Crestview Ave. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-012

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1932. It is rectangular in plan with a low-pitch side gable roof, clad in clay tile. The primary façade is asymmetrical. The walls are clad with smooth stucco. The windows are vertical wood casement windows and triple sash doors. Character-defining features include an interior chimney slightly elaborated in front bricked patio courtyard with two small vents on the roof, decorative window grilles, and an arched Porte Cochere. Alterations include the addition of a detached garage with a pergola/den added in 1934 and 1937 respectively with flat composition roofing. Landscaping consist of a lawn, large old camellias, and dracaena. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1932
City of Glendale Building Permit Records

*P7. Owner and Address:
LEO E & PATRICIA L GRIM
1008 CRESTVIEW AVE
GLENDALE CA 91202-1018

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1009 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1009 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-021

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the English Tudor Revival style, constructed in 1926. It is rectangular in plan with a steeply-pitched multiple-gabled roof with swept gable over front entry, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. First-floor fenestration consists of casement divided-light windows. Second-floor fenestration consists of vinyl casement windows and two diamond-paned windows constructed of wood. The door is recessed and constructed of wood. Character-defining features are brick chimney, wood shutters, steeply-pitched roof swept roof over entry porch, and minimal eave overhang. No discernible alterations. Landscaping consists of sloped front lawn, mature trees, and concrete steps leading to entry. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
City of Glendale Building Permit Records

*P7. Owner and Address:
DIANNE M DEANGELIS TRUSTEE
1009 CRESTVIEW AVE
GLENDALE CA 91202-1017

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1012 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1012 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-011

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family one-story residence designed in the Spanish Colonial Revival style, constructed in 1932. It is L-shaped in plan with a low-pitched cross-gable roof, clad in clay tile. The primary façade is asymmetrical. The walls are clad with smooth stucco. Windows include a large picture window with decorative iron grille work and rusticated stone surround and two fixed diamond-shaped openings. The double vertical door exhibits molded wood panels below a curved row of turned spindles. Character-defining features include projecting stepped arched entry portal with two projecting decorative moldings, attached garage with paneled door, exposed rafter tails and narrow molded frieze detail, and two decorative open work wood recessed window grilles. Landscaping consists of large pine tree, lawn, irregular stepping stone pathway, and planting areas by structure. The overall integrity of the building is good to excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1932
City of Glendale Building Permit Records

*P7. Owner and Address:
SHAYE K HARBER
1012 CRESTVIEW AVE
GLENDALE CA 91202-1018

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1013 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1013 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-022

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Mediterranean Revival style, constructed in 1926. It is square in plan with a medium-pitch hipped roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical with a balcony. The windows are casement constructed of wood; one window is arched. The single arched door is wood with stonework door surround. Character-defining features are tile roof, arched doorway, smooth stucco, and decorative chimney. Alterations include an added on covered front porch permitted in 1997. Landscaping consists of lawn with retaining shrubs, Saltillo tile steps and front entrance. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
Los Angeles County Assessor

*P7. Owner and Address:
MORGAN TRUST 2006-A4 JP
1013 CRESTVIEW AVE
GLENDALE CA 91202-1017

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1015 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1015 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-023

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the English Tudor Revival style, constructed in 1925. It is irregular in plan with a multi-gabled roof, clad in faux wood shingles. The walls are clad in rough stucco with accents of brick and half timbering. The primary façade is asymmetrical. The windows are wood divided-light casement and fixed aluminum. Character-defining features are steeply-pitched roof, half-timbering, brick, and chimney. Alterations include the addition of two bedrooms, bathroom, family room, dining room, and remodel kitchen in 1967. Landscaping consists of curved brick walkway, and two mature trees. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
City of Glendale Building Permit Records

*P7. Owner and Address:
DONALD G & SUSAN D BARLOW
1015 CRESTVIEW AVE
GLENDALE CA 91202-1017

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1018 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1018 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1938. It is irregular in plan with a cross-gable and hip roof, clad in asphalt shingles. The primary façade is asymmetrical. The walls are clad with smooth stucco with decorated verge board on the primary gable and one pediment of horizontal wood-lap siding. The windows include a prominent three-sided bay window with fixed diamond-pane leaded sashes beneath a shed roof hood. Other windows are wood casement or metal sliders with one small stained glass bath window. The main entry features a covered front porch with a molded paneled door that features a small medallion on lower panel. Character-defining features include a brick chimney with small band of brick trim and a Porte Cochere with shed roof. Landscape consists of a lawn with planter beds set in front of low hedge with large old growth tree, Australian fern and smaller plants, and annuals. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
BRIAN E & ANGELA N BATTLES
1018 CRESTVIEW AVE
GLENDALE CA 91202-1018

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 902 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 902 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-023

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence built in the Minimal Traditional style, constructed in 1948. It exhibits an L-shaped plan with a low-pitched cross-gable asphalt shingle roof. Attached two car garage projects toward the street and includes a small-enclosed breezeway. The primary façade is asymmetrical with walls clad in smooth stucco while original redwood detail is covered with brick veneer. The windows are vinyl sliding, fixed single pane, and bay window. Details include a front porch recessed under roof overhang and an off center brick chimney. The small curved driveway is landscaped on both sides with lawn, Australian fern, red flax, climbing vine, and hibiscus. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1948
City of Glendale Building Permit Records

*P7. Owner and Address:
LESLIE FLEISCHER TR
902 CRESTVIEW AVE
GLENDALE CA 91202-1016

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 906 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 906 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-022

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence built in the Minimal Traditional style, constructed in 1949. It is L-shaped in plan with a hip roof clad with asphalt shingles. The walls are clad in wood-lap. The primary façade is asymmetrical. The windows include one fixed casement constructed of steel at the front, steel and vinyl casement at west façade. The four-panel door with sidelights is constructed of wood. Character-defining features include concrete slab porch, curved planter bed, and curved entry concrete walkway. Alterations include a family room addition on the eastern portion of the primary façade permitted in 1998, installation of a non-original front door flanked by wood panels and sidelights, and chimney reinforcement with stucco finish. Landscaping consists of a lawn, birch trees, and flowering annuals. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1949
City of Glendale Building Permit Records

*P7. Owner and Address:
KIRTLYE L PARKER TRUST
906 CRESTVIEW AVE
GLENDALE CA 91202-1016

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 910 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 910 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-021

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Modern style, constructed in 1948. It is rectangular in plan with a very low-pitch side-gable roof, clad in rolled asphalt. The walls are clad in concrete block with accents of wood batten and board siding. The windows are casement constructed of wood. The recessed side facing front door is constructed of wood. Character-defining features include attached one-car garage with contemporary door, trellis canopy above window, and brick chimney. Landscape includes Fan Palm, Camellias, and lawn. Alterations include the conversion of the original carport into a family room constructed in 1965 and the addition of two bedrooms and service porch added in 1955. The additions occurred within the period of significance and the additions did not compromise the massing of the building. The overall integrity of this building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1948
City of Glendale Building Permit Records

*P7. Owner and Address:
NANCY CASOLARO
1046 LAVENDER LN
LA CANADA FLINTRIDGE CA 91011-2337

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 915 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 915 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-014

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the English Tudor Revival style, constructed in 1926. It is irregular in plan with a steeply-pitched cross-gabled roof, clad in asphalt shingles. The walls are clad in smooth stucco with brick chimney. The façade is asymmetrical. The windows are casement divided-light constructed of wood; one fixed window at first floor contains decorative patterned glass that does not appear original. Character-defining features are main entrance recessed within entry porch with arched openings, Porte Cochere, steeply-pitched roof, minimal eaves, and stucco steps with metal railing. The building appears to be unaltered. Landscaping consists of sloping and retained lawn. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
City of Glendale Building Permit Records

*P7. Owner and Address:
JOHN & CAROL S MCSHANE
915 CRESTVIEW AVE
GLENDALE CA 91202-1015

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 916 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 916 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-016

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Ranch style with Tudor influence, constructed in 1950. It is irregular in plan with a cross-gable roof, clad in asphalt shingles. The primary façade is asymmetrical. The walls are clad in smooth stucco with brick and wood-lap in gable ends. The main entry features a covered porch with double glazed lights and paneled apron door with sidelights. Character-defining features include two gable dormers with casement windows, exposed rafter tails, half timbering, exterior decorative brick chimney and a side-gable Porte Cochere. Alterations include metal sliding windows, an addition to the rear of the building in 1986 and a pool equipment storage shed added in 1988. Landscape includes brick planter beds with large camellias, bird-of-paradise, azaleas, brick stairs, and lawn. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1950
City of Glendale Building Permit Records

*P7. Owner and Address:
ANITA H BACON
916 CRESTVIEW AVE
GLENDALE CA 91202-1016

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 920 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 920 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style with French influence, constructed in 1940. It is L-shaped in plan with a hip roof, clad in asphalt shingles. The primary façade is asymmetrical. The walls are clad in smooth stucco. The window facing the street is fixed divided-light constructed of wood. Other windows are aluminum hung with internal grids. Character-defining features are exposed rafter tails, brick chimney, arched wall dormer, and decorative wood shutters. Landscaping consists of low brick planting borders with large Australian fern, Camellias, Gardenia hedge and low wrought iron fence, with lawn and cement walkway to entrance. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1940
City of Glendale Building Permit Records

*P7. Owner and Address:
HASMIK TOVMASIAN
920 CRESTVIEW AVE
GLENDALE CA 91202-1016

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 921 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 921 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the English Tudor Revival style, constructed in 1926. It is square in plan with a steeply-pitched side-gable roof with multiple front gables, clad in asphalt shingles. The walls are clad in rough stucco with accents of half-timbering. The primary façade is asymmetrical. The windows are fixed and casement divided-light constructed of wood; the single panel door with diamond-shaped window is constructed of wood. Character-defining features are inset porch with arched opening sheltering main entrance, chimney, steeply-pitched roof, close eaves, and decorative vents. The building appears to be unaltered. Landscaping consists of sloping lawn and mature tree. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
City of Glendale Building Permit Records

*P7. Owner and Address:
SIMON J WAKLEY
921 CRESTVIEW AVE
GLENDALE CA 91202-1015

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 925 Crestview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 925 Crestview Ave. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-016

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Mediterranean Revival style, constructed in 1926. It is square in plan with a low-pitched hipped roof, clad in clay tile. The walls are clad in rough stucco with accents of stone on lower portion of front façade. The primary façade is asymmetrical. The windows are a variety of divided-light double-hung and casement, arched and rectangular constructed of wood; the nine-panel door has a diamond-shaped light above entry and is constructed of carved wood. Character-defining features are notched cast-stone door surround above the main entry, recessed arched window, and decorated chimney. No discernible alterations. Landscaping consists of sloped front lawn, mature palm tree, and diagonal stepped walkway leading to front steps with landing; has walled in side-garden. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
City of Glendale Building Permit Records

*P7. Owner and Address:
MARK KAELLER
925 CRESTVIEW AVE
GLENDALE CA 91202-1015

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1001 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1001 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-001-022

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence, on a corner lot with two street façades, designed in the Spanish Colonial Revival style, constructed in 1932. It is irregular in plan with a cross-gabled roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. There is a variety of window types, all constructed of wood and include arched fixed, horizontal sliders, and double-hung divided-lights. Character-defining features are asymmetric recessed front porch with multiple arched openings, decorative wrought iron gates, picture window with wrought iron balustrade and capped by decorative iron frieze, half height stucco wall enclosing front courtyard and rear patio, decorative venting on front gables, rear patio covered with clay tile overhang, porch supports decorated with stucco lip, end posts of half height stucco walls, exposed rafter tails, and decorative tile. Alterations include rear patio extension in 1970 and addition of a garden wall in 2002. Landscaping consists of a mature tree in the front lawn and a curved pathway leading from the sidewalk to the entranceway. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1932
Los Angeles County Assessor

*P7. Owner and Address:
JOSE L BORRAEZ
1001 CUMBERLAND RD
GLENDALE CA 91202-1023

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1007 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1007 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-021

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1937. It is L-shaped in plan with a hipped roof, clad in asphalt shingles. The walls are clad in smooth stucco with accents of wood-lap. The primary façade is asymmetrical. The windows are double-hung divided-lights constructed of wood. Character-defining features are decorative wooden shutters, horizontal wood-lap on top half of projecting wing, and door with pediment outlined with wood-lap. Alterations include façade window replacement in 1995. Landscaping consists of a mature tree at the edge of the front lawn. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1937

City of Glendale Building Permit Records

*P7. Owner and Address:

JOHN C & DIANE CHEVALIER

1007 CUMBERLAND RD

GLENDALE CA 91202-1023

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

5/26/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1010 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1010 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-008-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family residence and a one-story residence with a two-story rear addition designed in the Spanish Colonial Revival style, constructed in 1938. It is rectangular in plan with a low-pitched hipped and gable roof, clad in clay tile. The walls are clad with smooth stucco. The façade is asymmetrical. The windows are non-original vinyl, horizontal-sliding and the non-original door is flanked by a stained glass side-light on one side. Character-defining features are the tiled roof and an exterior half height walled courtyard with fountain in front. Alterations include a two-story side-gable addition at the rear of the residence, a two-stall garage with a flat tiled roof, vinyl windows at the rear of the property, and a wrought iron gate. Landscaping consists of a tiled walkway that cuts through a flat lawn at an angle with a wrought iron gate leading into a half height stucco walled courtyard, rosebushes and low plants surround the structure. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1938
City of Glendale Building Permit Records

*P7. Owner and Address:
DEBBIE TRAN
1010 CUMBERLAND RD
GLENDALE CA 91202-1024

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
4/21/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1011 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1011 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-001-020

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1947. It is rectangular in plan with a low-pitch hipped roof, clad in concrete tile. The walls are clad in smooth stucco with accents of brick. The primary façade is asymmetrical. The windows are double-hung divided-lights, constructed of wood; the non-original door is centrally positioned on the primary façade. Character-defining features are defined partial-width inset porch supported with slender wood beams, primary entrance located on the porch, projecting three-sided bay window centered on protruding façade, wide brick chimney attached to the exterior side, and diagonal wood grill on porch. Alterations include the enclosure of part of front porch for dining room in 1985, door replacement with contemporary style, addition of canvas awning over prominent bay window, new wood shutters on front façade windows, and new wrought-iron gate and porch railing. Landscaping consists of several mature trees scattered around property, brick walkway extending from the driveway to the entranceway, and brick planters outlining the front façade. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1947
City of Glendale Building Permit Records

*P7. Owner and Address:
ARMINE NAZARIAN
1011 CUMBERLAND RD
GLENDALE CA 91202-1023

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1014 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1014 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-008-008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family residence and a one-story residence, designed in a Spanish Colonial Revival style, constructed in 1925. It is rectangular in plan with a cross-gable roof, clad in S-tile. The walls are faced with smooth stucco and the façade is symmetrical. The windows are non-original aluminum double-hung and fixed, one bay window faces west and the non-original door is recessed within the entry porch with arched opening. Character-defining features are the symmetrical arched entryway which is echoed in the half round shaped lintels over symmetrically placed windows and a quatrefoil vent in the front facing gable and a square tower with hip roof. Alterations include bathroom addition in 1936 and installation of aluminum windows. Landscaping consists of palm trees, walls with red brick on west of driveway and partly along a curved entry walkway which is flanked by low flowering bushes through flat lawn. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
City of Glendale Building Permit Records

*P7. Owner and Address:
NANCY SUMNER
1014 CUMBERLAND RD
GLENDALE CA 91202-1024

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 4/21/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1015 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1015 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-001-019

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1949. It is square in plan with a low-pitched hip roof, clad in asphalt shingles. The walls are clad in wood-lap with accents of smooth stucco at the base. The primary façade is asymmetrical. The windows are primarily double-hung with one fixed single pane, all constructed of wood; the door is situated to the left side of the façade, in a recessed entry porch. Character-defining features are horizontal emphasis projected through the low-pitch hipped roof, wood-lap, and exposed rafter tails. Landscaping consists of one mature tree in the front lawn dominating the property. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1949
City of Glendale Building Permit Records

*P7. Owner and Address:
HARTLYN & SHERRIE HORIE TR
1015 CUMBERLAND RD
GLENDALE CA 91202-1023

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1017 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1017 Cumberland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-018

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1928. It is irregular in plan with multiple gabled, shed and hipped roof styles, all clad in clay tile. The walls are clad in smooth stucco. The primary façade is slightly obscured due to intensity of foliage. The windows are primarily casement, with some fixed, constructed of wood and steel. Character-defining features are wrought iron ornamentation on second story portholes in Porte Cochere and on first floor portholes, exposed rafter tails visible on first and second levels, clay tile clad Porte Cochere with iron and glass light fixture, front porch supported by stuccoed square columns, and projecting roof beams. Alterations include installation of a new door in 1965. Landscaping consists of heavy landscaping obscuring the front of the house, landscaping area outlined by tiered stucco and brick retaining wall, mature palm trees, and a red-tiled sloped driveway, which leads to the entranceway. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1928
City of Glendale Building Permit Records

*P7. Owner and Address:
EDMOND & RUBINA H MANOUCHEHRI
1017 CUMBERLAND RD
GLENDALE CA 91202-1023

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1020 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1020 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-008-007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family residence and a one-story residence, designed in a Spanish Colonial Revival style, constructed in 1928. The house is L-shaped in plan and the cross-gable roof is clad in clay tile with exposed rafter tails and projecting roof beams. The walls are faced with smooth stucco and the façade is asymmetrical. The windows are wood divided-light casement and double-hung, with wood lintels. The entryway is east facing covered by a porch with a red brick column. The door is original wood with a single panel. Character-defining features are a small stucco chimney on west wall and the east facing porch entryway with stuccoed vent, enclosed in a red brick patio surrounded by a half height stucco wall with gate. Landscaping consists of low palm trees, concrete and red brick driveway, red brick path leading from driveway to gated patio entrance, and flat lawn to sidewalk. The pathway entrance is flanked by two low brick columns topped with lanterns. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1928

City of Glendale Building Permit Records

*P7. Owner and Address:

ROBERT & HILDA FIEDLER

1020 CUMBERLAND RD

GLENDALE CA 91202-1024

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

4/21/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1021 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1021 Cumberland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-017

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1925. It is irregular in plan with a multiple gabled roof, clad in clay tile. The walls are clad in rough stucco. The facade is asymmetrical. The windows on the primary façade are primarily arched frame, fixed divided-light windows, constructed of wood; the door is arched constructed of wood and located in a defined entry wing. Character-defining features are two sets of tripartite arched windows with a larger central frame flanked by smaller outer frames, wrought iron railing outlining the front porch. Landscaping consists of several mature palm trees and fledgling palms, planted directly in front of the house and a mature tree in the center of the front lawn. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
City of Glendale Building Permit Records

*P7. Owner and Address:
MELINE PAPAIZIAN
1021 CUMBERLAND RD
GLENDALE CA 91202-1023

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1022 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1022 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-005-012

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family residence and a one-story residence designed in a Spanish Colonial Revival style, constructed in 1928. It is L-shaped in plan with cross-gable roof, clad in clay tile. The walls are faced with smooth stucco and the facade is asymmetrical. The windows are wood divided-light fixed and casement including tripartite window with fixed center sash flanked by two casements. The main entryway faces east under a covered porch with wooden posts and a second door with four glass panels in upper half faces front. Character-defining features are clay tile roof, exterior courtyard of red brick surrounded by red brick wall and metal gate, an outside stucco chimney located in the inside of the L-shape, and a round vent in the front facing gable wall. Alterations include red brick wall and gates to patio and driveway. Landscaping consists of palm trees, shrubs and bushes, concrete driveway and path with red brick accents, flat lawn to sidewalk. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1928
City of Glendale Building Permit Records

*P7. Owner and Address:
HOVANES J & ZAVEN & AN KALAYJIAN
1022 CUMBERLAND RD
GLENDALE CA 91202-1024

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 4/21/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1026 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1026 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-005-011

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family residence and a one-story residence designed in a Minimal Traditional style, constructed in 1939. It is L-shaped in plan with a hip roof, clad in asphalt shingles. The walls are faced with wood-lap and the facade is asymmetrical. The windows are double-hung and divided-light with a divided-light projecting bay window prominently placed on projecting wing. The main entryway faces east and the door is wood paneled. Character-defining features are prominent bay window and decorative wood shutters, a covered porch with wrought iron supports, and a brick chimney on west side front. Landscaping consists of driveway with grass median on east side, mature tree to west and large circular planter center of lawn. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1939
Los Angeles County Assessor

*P7. Owner and Address:
FRANK G & MELINDA M KITCHIN
1026 CUMBERLAND RD
GLENDALE CA 91202-1024

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 4/21/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1027 Cumberland Rd.

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 1027 Cumberland Rd. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
 Los Angeles County Assessor's Parcel Number: 5629-001-016

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the English Tudor Revival style, constructed in 1928. It is rectangular in plan with a steeply-pitched multiple gabled roof, clad in asphalt shingles. The walls are clad in smooth stucco with accents of brick. The primary façade is asymmetrical. The front façade windows are primarily fixed, single pane of wood frame with diamond-pane transom above. Character-defining features are half-timbered gable detailing, brick window and door surrounds on prominent front gable wing, half height wall enclosing front porch with brick detailing, diamond shaped leaded glass transoms above fixed windows, shed dormer with three windows and prominent stucco balustrade, exposed rafter tails, steeply-pitched front gables, prominent brick chimney attached to side exterior, and tall and narrow venting in dominant front gable wing. Landscaping consists of mature spruce in front of dominant front gable. The overall integrity of the building is excellent.

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

***P6. Date Constructed/Age and Source:** Historic Prehistoric
 Both

1928
City of Glendale Building Permit Records

***P7. Owner and Address:**
ROBERT M & MARTHA H HAGER
1027 CUMBERLAND RD
GLENDALE CA 91202-1023

***P8. Recorded by:** (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

***P9. Date Recorded:** 5/26/2011

***P10. Survey Type:** (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

***P11. Report Citation:** (Cite survey report and other sources, or enter "none.") None

***Attachments:** NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1030 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 1030 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-005-010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1925. It is square in plan with a hipped roof at front elevation and flat roof with parapet to the rear, both clad in S-tile. The walls are clad with smooth stucco. The façade is asymmetrical. The windows are arched and divided-light with wood framing. The main entry is an exterior courtyard surrounded by walls with two arched openings that are gated. Character-defining features are the arched entryways in the courtyard walls, arched main front window, arched entry on west side, exterior stucco chimney on east gabled wall, vent in hipped front gable, and iron gated driveway. Alterations include window replacement on north side. Landscaping consists of brick path in criss-cross formation in front of courtyard entry with a fountain in center, tiled driveway, mature trees and palm tree, various plants and low concrete wall topped with iron railing. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
City of Glendale Building Permit Records

*P7. Owner and Address:
ANDREW GOLIN
1030 CUMBERLAND RD
GLENDALE CA 91202-1024

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 4/21/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1031 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1031 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one- and two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1925. It is U-shaped in plan with a multiple gabled roof, clad in clay tile. The walls are clad in rough stucco. The façade is asymmetrical. The windows on projecting front wings are fixed pane windows and on the central block are divided-light casements, all constructed of wood. Character-defining features are heavily textured stucco exterior, front arched divided-light picture window, shaped wing wall, chimney of same rough textured stucco attached to side exterior, and front courtyard formed by the U-shaped dwelling design. Alterations include second story addition above garage in 1926. Landscaping consists of a mature palm in front yard, several citrus trees in front, and concrete walkway gently winding up the grassy knoll to the entrance. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925

Los Angeles County Assessor

*P7. Owner and Address:

LAMBERT & PIETERNELLA PEEMAN

1031 CUMBERLAND RD

GLENDALE CA 91202-1023

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

5/26/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 839 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 839 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-004-002

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1949. It is L-shaped in plan with a front gable and side gable roof, clad in asphalt shingles. The walls are clad in smooth stucco with wood shingle siding above and a low red brick wainscot veneer on the primary façade. The primary façade is asymmetrical. The windows are horizontal sliding and a fixed single pane constructed of aluminum. Character-defining features include are original window openings with decorative hood molding above each window, small porch with decorative columns, tripartite picture window, basement garage, combination of exterior materials, molding above windows, and decorative air vents. Alterations include contemporary door and louvered windows. Landscaping consists of mature trees, lawn, and various plantings. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1949
City of Glendale Building Permit Records

*P7. Owner and Address:
ANGELA BUICKIANS
PO BOX 4451
GLENDALE CA 91222-0451

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 843 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 843 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-004-003

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style with stylized trim, constructed in 1942. It is rectangular in plan with a cross-gable roof, clad in composition shingle. The walls are clad in smooth stucco with a low masonry wainscot veneer across the primary façade. The primary façade is symmetrical. The windows include a three-sided bay window on the front façade, single pane fixed, and horizontal sliding windows constructed of wood and aluminum. The six paneled door is constructed of wood. Character-defining features include bay window, masonry wainscot veneer, and decorative shutters. Landscaping consists of large mature tree, various plantings, planter wall, and concrete stair capped with brick. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1942
City of Glendale Building Permit Records

*P7. Owner and Address:
CYNTHIA M HOGAN TR
843 CUMBERLAND RD
GLENDALE CA 91202-1050

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 847 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 847 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-004-004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style with Modern influences, constructed in 1950. It is L-shaped in plan with a hip roof, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical with a centrally located recessed entry, which is defined by a curved corner and flanked by a large full-height corner plate glass window. A red brick planter is at the front façade. The windows are fixed double-hung and divided-light constructed of wood; the door is constructed of wood and glass. Character-defining features include the corner glass window with no frame, rounded façade to the left of front door, framing around windows. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1950
City of Glendale Building Permit Records

*P7. Owner and Address:
RALPH A & PAMELA M RUST
847 CUMBERLAND RD
GLENDALE CA 91202-1050

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5B

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 850 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 850 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-013-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1929. It is irregular in plan with a low-pitch multiple gable roof, clad in clay tile. The walls are clad in stucco. The primary façade is asymmetrical. The windows are divided-light casement constructed of metal with one arched picture window of metal facing walled courtyard. Character-defining features are stucco chimney, overhanging second story, recessed entry/door, exterior courtyard enclosed by half height wall, round vents in gable ends, cantilevered balcony with wood posts and balustrade and exposed beams, exposed rafter tails, and recessed entry. The residence appears to be unaltered. Landscaping consists of mature trees including sycamores, lawn area, hedges lining the path to the main entrance and elaborate plantings throughout the property. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1929
Los Angeles County Assessor

*P7. Owner and Address:
ROBERT W & JOANNA C HINKEL
850 CUMBERLAND RD
GLENDALE CA 91202-1052

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 853 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 853 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-004-005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1923. It is rectangular in plan with a front and side gable roof, clad in clay tile toward the front of the house and a flat roof with clay tile parapet walls in the back. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are fixed and divided-light casements constructed of wood. Character-defining features include the small arched covered porch with arched doorway, tiled roof, prominent picture window, stucco, and wrought iron grille work. Landscaping consists of mature trees, lawn, and various plantings. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1923
City of Glendale Building Permit Records

*P7. Owner and Address:
CHARLES & PAULA UNGER
853 CUMBERLAND RD
GLENDALE CA 91202-1050

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 860 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 860 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-012-021

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This sprawling Ranch style house, constructed in 1952 is rectangular in plan and is situated on a corner lot oriented toward Cumberland Road. The façade is asymmetrical. Features include carved bargeboard over a gable on hip roof, overhanging eaves with exposed rafter tails with rounded ends, inset porch with wooden porch posts with diagonal braces, and a decorative chimney with accenting brick molding along the top. The exterior cladding is a combination of wood, stucco, and brick. Windows are original wood with decorative wood shutters and are rectangular and diamond-shaped divided-lights. The roof is a low-pitched gable-on-hip. No alteration permits are on file and no alterations were visible in the field. The original integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1952
City of Glendale Building Permit Records

*P7. Owner and Address:
FREDERICK K & MARTHA I MILLER
860 CUMBERLAND RD
GLENDALE CA 91202-1051

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 3/20/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 863 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 863 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-003-001

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence originally designed in the Monterey Revival style with Minimal Traditional elements, constructed in 1936. Dramatic remodel in 2005/6 includes complete restuccoing, removal of siding and shutters, alteration of balcony, and installation of new front door and windows. As a result of the remodeling, the house has no discernible architectural style. Other alterations include a family room addition at the rear of the residence in 1979. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
COUNTRYWIDE BANK FSB
863 CUMBERLAND RD
GLENDALE CA 91202-1049

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 3/30/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 869 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 869 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-003-002

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the English Tudor Revival style, constructed in 1935. It is rectangular in plan with a front and cross hipped gable roof, clad in wood shingles. The walls are clad in smooth stucco with a red brick veneer on the first story of the primary façade. The primary façade is asymmetrical. The windows are horizontal sliding set in groups of three and include three-sided bay windows constructed of metal; the door is revival style constructed of wood. Character-defining features include half timbering on the second story, quoins, Porte Cochere and wooden corbels under second story. Landscaping consists of mature tree, sloping lawn, driveway with grass center aisle, and various plantings. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
City of Glendale Building Permit Records

*P7. Owner and Address:
DAVID H CATLIN
869 CUMBERLAND RD
GLENDALE CA 91202-1049

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 3/30/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 873 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 873 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-003-004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1927. It is Rectangular in plan with a low-pitched gable and hip roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. Character-defining features include the balcony, wrought iron railings, a Porte Cochere, a recessed arched entry, stucco wall vents, and arched door with decorative glass. Alterations include the installation of aluminum windows on the second story. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
8/31/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1927
Los Angeles County Assessor

*P7. Owner and Address:
DAVID CATLIN
873 CUMBERLAND RD
GLENDALE CA 91202-1049

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
3/30/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 877 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 877 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one to two-story single-family residence designed in the Spanish Colonial style, constructed in 1927. It is rectangular in plan with a multiple level low-pitch cross-gable roof, clad in clay tile. The walls are clad in textured stucco. The entrance is recessed beneath an exterior staircase that forms a small entry porch. The porch has a parabolic arch opening with a decorative cast stone surround. The primary façade is asymmetrical. The windows are divided-light casement constructed of wood; the door is constructed of wood. Character-defining features include the parabola entryway with an exterior staircase, decorative cast stone trim around entryway and front window, exposed rafter tails, and a balcony. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1927
City of Glendale Building Permit Records

*P7. Owner and Address:
PATRICIA MESSINA
877 CUMBERLAND RD
GLENDALE CA 91202-1049

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 880 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 880 Cumberland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-012-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1948 on a sloping site with garage at the rear. It is L-shaped in plan with a hipped roof, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are mostly divided-light double-hung wood sash windows set in pairs. There is a three-sided bay window with diamond-shaped glazing in the projecting section of the front façade. Character-defining features include Porte Cochere, inset front porch, brick chimney, wood shutters, exposed rafter tails. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1948
City of Glendale Building Permit Records

*P7. Owner and Address:
MICHAEL R GAMMELL
880 CUMBERLAND RD
GLENDALE CA 91202-1051

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 881 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 881 Cumberland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-006

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the American Colonial Revival style, constructed in 1937. It is rectangular in plan with a side-gable roof, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is symmetrical and is three bays wide. The windows are double-hung (six over six) divided-light constructed of wood; the door is a wood five light paneled door. Character-defining features include front gabled wall dormers above second story windows, recessed entrance in center bay on first story with a simple surround, windows with shutters in outer bays on both stories, and band course between first and second stories. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1937
City of Glendale Building Permit Records

*P7. Owner and Address:
FRED M & MARY M SMITH TR
881 CUMBERLAND RD
GLENDALE CA 91202-1049

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 885 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 885 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1930. It is irregular in plan with multiple low-pitch shed and gable roofs, clad in clay tile. The walls are clad in stucco. The primary façade is asymmetrical. The windows are fixed and casement sash divided-light constructed of wood; the door is constructed of wood with a sidelight. Character-defining features include the carved alcove for recessed windows, balconies, eave brackets, exposed rafter tails, exterior courtyard, large picture window, corbels beneath the second story projection, and side arched wing wall. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1930
Los Angeles County Assessor

*P7. Owner and Address:
JARRETT S ANDERSON
885 CUMBERLAND RD
GLENDALE CA 91202-1049

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 886 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 886 Cumberland Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-012-010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story single-family home was designed in the Ranch style with Modern elements and constructed in 1958. The house is large and sprawling horizontally and wraps around the corner lot with a low-pitch hip roof, clad in asphalt shingles. The original windows are metal casement and fixed and include ribbon and corner windows. The wide front door opening is sheltered by an inset front porch opening fit with a pair of large solid wood double doors with brass kick plate. The exterior finish is stucco with wood board-and-batten and accents of flagstone veneer. The wide, wood slab double front door opens in the center. Three low-raise steps lead to an inset porch. Landscaping consists of various plantings, lawn, and concrete walkway stepped down from the sidewalk. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1958
City of Glendale Building Permit Records

*P7. Owner and Address:
NELLY OGANESIAN
886 CUMBERLAND RD
GLENDALE CA 91202-1051

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 900 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 900 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-009-001

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Ranch style, constructed in 1951. It is L-shaped in plan with a low-pitch hip roof, clad in composition shingles. The primary façade is asymmetrical. Walls are clad in smooth stucco, dating to 2005. Windows are sliding and fixed, constructed of vinyl. Alterations are extensive, including cladding, roof, addition of foyer, and relocation of entry door. Landscaping consists of a lawn, which slopes downwards toward the house. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1951
City of Glendale Building Permit Records

*P7. Owner and Address:
GEORGE & BELLA ISSAIANS
900 CUMBERLAND RD
GLENDALE CA 91202-1022

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 901 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 901 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-002-001

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence, on a corner lot with two street facades, designed in the Spanish Colonial Revival style, constructed in 1933. It is L-shaped in plan with a low-pitched cross-gable and flat roof, clad in clay tile. The walls are clad in smooth stucco with stone accents on the foundation. The primary façade is asymmetrical. The windows are primarily divided-light casements accented by several fixed and arched windows, all constructed of wood. Character-defining features are decorative iron eave brackets, exposed rafter tails, a covered front porch with arcaded openings, a half height brick wall enclosing the front courtyard area, a half height stucco wall enclosing the side courtyard, two chimneys with decorative caps, and decorative iron work on the patio railings and entrance gate. Alterations include a new brick retaining wall enclosing the front courtyard and a side addition consistent with the architecture of the main house. Landscaping consists of lush wall vines and fledgling trees and a stone step walkway to the entrance gate from the sidewalk. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1933
City of Glendale Building Permit Records

*P7. Owner and Address:
DONALD M & STEPHANIE L TOVAR
901 CUMBERLAND RD
GLENDALE CA 91202-1021

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 909 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 909 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-002

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1929. It is rectangular in plan with a low-pitched multiple gabled roof, clad in clay tile. The walls are clad in rough stucco. The primary façade is asymmetrical. The windows include rectilinear fixed single pane, divided-light casements, and arched fixed pane windows constructed of wood. The door is situated off the enclosed front patio, and appears to be the original wooden door. Character-defining features are half height wall enclosing front patio, arched picture window above a protruding stucco sill dominating the front gabled wing, overhanging second-story supported by exposed wooden beams, exposed rafter tails, second story balcony with wood balustrades and beams, and circular venting on front gabled facades. Significant landscaping consists of a large sycamore tree dominating the front yard. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1929
Los Angeles County Assessor

*P7. Owner and Address:
REJEAN & DENISE M BOURDAGES
909 CUMBERLAND RD
GLENDALE CA 91202-1021

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 910 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 910 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-009-002

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed with elements of Minimal Traditional style, constructed in 1936. It is L-shaped in plan with a steeply-pitched cross-gable roof clad in asphalt shingles. The walls are clad in smooth stucco with accents of wood-lap. The primary façade is asymmetrical. The windows are divided-light casement and fixed constructed of wood. Character-defining features include fixed decorative shutters, decorative vents on wood-lap, and a brick chimney. Landscaping consists of a perennial border and mature trees. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
MICHAEL C & LYNETTE K DAVIS
910 CUMBERLAND RD
GLENDALE CA 91202-1022

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 911 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 911 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-003

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the English Tudor Revival style, constructed in 1926. It is L-shaped in plan with a multiple gabled roof, clad in asphalt shingles. The walls are clad in rough stucco. The primary façade is asymmetrical. The windows are divided-light casement windows constructed of wood. Character-defining features are shutters flanking the façade windows, wrought iron stair railings, and a wide brick chimney prominently situated adjacent to the front door. Alterations include reconstruction of front porch in 1991 and reconstruction of chimney in 1991. Landscaping consists of a large mature sycamore tree and a brick pathway leading from driveway to front steps. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
City of Glendale Building Permit Records

*P7. Owner and Address:
RALPH E & MARY M DAY
911 CUMBERLAND RD
GLENDALE CA 91202-1021

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 914 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 914 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-009-021

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the French Eclectic style, constructed in 1925. It is rectangular in plan with steeply hipped roof, clad in asphalt shingles. The walls are clad in rough stucco with accents of wood-lap. The primary façade is asymmetrical. The windows are divided-light horizontally sliding constructed of wood and aluminum. Character-defining features are a steeply-pitched roof, a weathervane, exposed rafter tails, and fixed decorative shutters. Landscaping consists of a curved walkway, lamppost, and mature trees. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
City of Glendale Building Permit Records

*P7. Owner and Address:
ARAM H KRIKORIAN
914 CUMBERLAND RD
GLENDALE CA 91202-1022

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 917 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 917 Cumberland Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-002-004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the French Eclectic style, constructed in 1926. It is L-shaped in plan with a clipped cross-gable roof, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical and features a small exterior courtyard with half height wall. The windows are casement divided-light constructed of wood; the paneled door is constructed of wood. Character-defining features are stuccoed chimney, eyebrow dormer, gable dormer, steeply-pitched roof, and notched courtyard half height wall. The residence appears to be unaltered. Landscaping consists of mature tree and lawn. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
City of Glendale Building Permit Records

*P7. Owner and Address:
JOHN F & KATHRYN G MCLAUGHLIN
917 CUMBERLAND RD
GLENDALE CA 91202-1021

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5B

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 922 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 922 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-009-022

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1932. It is rectangular in shape, with a low-pitch gabled roof clad with clay tile. The walls are clad with smooth stucco. The primary façade is asymmetrical. Windows include an arched single-paned, fixed window made of wood dominates the façade and a divided-light bay window made of wood on the west side of the house. The main front entry door features a tower element with an urn on top, while the paneled wood door is trimmed in decorative, painted tile; there is also an arched side-entry door. Character-defining features include a low-pitched tile roof, decorative vents, stained glass, exposed rafter tails and projecting root beams, wrought iron railings, exterior courtyard with decorative, painted tiles, and recessed arched exterior doorways and windows. Landscaping consists of a curved cement walkway, large mature trees, and many ferns. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1932
City of Glendale Building Permit Records

*P7. Owner and Address:
THOMAS & PAULA OKEEFE
101 N BRAND BLVD
GLENDALE CA 91203-2639

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 923 Cumberland Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 923 Cumberland Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence on a corner lot designed in the Minimal Traditional style, constructed in 1935. It is rectangular in plan with a low-pitch cross-gable roof, clad in asphalt shingles. The walls are clad in smooth stucco with accents of wood in the gable ends. The primary façade is asymmetrical. The windows are casement divided-light and projecting three-sided bay constructed of wood; the door is features sidelights. Character-defining features are projecting porch with low wall and wood columns and projecting bay window. Alterations include new door with sidelights replacing previous non-original door and a garden wall added in 1997 along the eastern elevation of the residence. Landscaping consists of mature trees, lawn, and extensive vegetation. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
Los Angeles County Assessor

*P7. Owner and Address:
ARTHUR P YIN
923 CUMBERLAND RD
GLENDALE CA 91202-1021

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1601 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1601 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-002-005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story single-family residence was constructed in 1950 and designed with elements of the Minimal Traditional and Ranch styles. Irregular in plan, the residence has a multiple gable roof with side-gable monitor roof with exposed rafter tails clad in shingles, painted brick walls with exposed mortar and wood siding in the gable ends. The façade is asymmetrical, with fixed wood windows, a diamond-paned leaded glass window and aluminum sliding windows. The character-defining features include the leaded glass picture window, a cupola topped by a weather vane, fixed shutters, exposed rafter tails, an open, wide porch with wood square columns and diagonal braces. Alterations include an addition to the south side of the original residence, featuring similar brick and exposed mortar walls, a gable-on-hip roof and aluminum slider windows (1964), and a newer cal-tile roof (1983). The residence is heavily landscaped with rose bushes, planter hedges and ivy berms. The integrity of the original structure is good, though the addition compromises the overall integrity of the residence.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1950
City of Glendale Building Permit Records

*P7. Owner and Address:
ROBERT & ELLEN FAREWELL
1601 GRANDVIEW AVE
GLENDALE CA 91201-1205

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1610 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 1610 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-005-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story single-family residence was constructed in 1926 in the Spanish Colonial Revival Style. It is rectangular in plan, with an asymmetrical façade. The roof is constructed of two side gables in a line, one slightly lower than the other, made of clay tiles. The walls are of rough stucco. The door is contemporary and there are casement, double-hung, and rounded arch windows, all with divided-lights. Two large rounded arch windows have divided fanlights and French door style openings. An exterior stairway with a wrought iron railing leads to a second story landing over the first floor entrance door. Character-defining features include the decorative lantern with wrought iron attachments on the side of the second story landing over the main entrance, a stucco-clad chimney and twelve decorative vents in the second floor of the front façade. The integrity of the house is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926

City of Glendale Building Permit Records

*P7. Owner and Address:

RICHARD T MUIRHEAD

1610 GRANDVIEW AVE

GLENDALE CA 91201-1206

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

4/21/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1616 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1616 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-005-008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story single-family residence was constructed in 1940 in the Minimal Traditional style. It is rectangular in plan with an asymmetric façade. The multi-hipped roof is composed of faux shakes. The walls are of smooth stucco, and portions of the façade have a low brick wainscot veneer. A covered porch is reached by a walkway leading to stairs set at an angle from the façade. A decorative wrought-iron post stands at the entry. The entrance consists of a three-paneled wood door. The front façade windows are steel multi-light. Remaining windows are wood divided-light, both casement and double-hung. Character-defining features include the bay window, the chimney with two brick stripes, and the brick veneer base and stoop. The integrity of the house is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1940
Los Angeles County Assessor

*P7. Owner and Address:
JAMES & CANDICE PICCIONE
1616 GRANDVIEW AVE
GLENDALE CA 91201-1206

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
4/21/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1624 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1624 Grandview Ave. City Glendale Zip 91201
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-001-013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1931. It is rectangular in plan with a hipped and side gabled roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are primarily divided-light casements, with some arched, fixed windows, all constructed in wood. Character-defining features are, wood shutters with diamond-shaped cut-outs, L-shaped porch, overhanging second story, exposed rafter tails, stained glass, and decorative iron work. No documented or observed alterations. Landscaping consists of extremely lush and heavy landscaping, stone walkway from sidewalk to the side entrance, and several mature trees including mature spruce and oak trees. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1931
City of Glendale Building Permit Records

*P7. Owner and Address:
PETER J RUSCH
1624 GRANDVIEW AVE
GLENDALE CA 91201-1262

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/2/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1625 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1625 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-002-004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story single-family residence was constructed in 1923 and designed in the Spanish Colonial Revival style. Basically rectangular in plan, the house features a low-pitch multiple gable, clay tile roof, smooth stucco walls, and casement and fixed wood windows. Character-defining features are a recessed pointed arch window (divided-light) framed by decorative tiles. Alterations include changing the original flat roof to a pitched roof (1946), a newer tile roof (1993), and a remodeled entrance room (1998). The landscaping features a circular driveway, mature magnolia and palms trees, and planted landscape beds/planters. The overall integrity of the residence is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1923
City of Glendale Building Permit Records

*P7. Owner and Address:
R GERARD & SUSAN M SPEHAR
1625 GRANDVIEW AVE
GLENDALE CA 91201-1205

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1629 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1629 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-002-003

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story single-family residence was constructed in 1953 and designed in the Ranch style. Irregular in plan, the house features a side gable roof, clad in cement tiles, and smooth stucco walls with a brick veneer base. The façade is asymmetrical. The windows include casement and divided-light including diamond-pane wood windows, and French doors along the front porch. The character-defining features include a hip roof cupola topped by a weather vane, exposed rafter tails, an open front porch with shed roof and squared wood columns and brick platform, fixed shutters, and a brick chimney. The landscaping consists of a circular driveway with brick ribbons, mature trees and lawn. The overall integrity of the residence is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1953
Los Angeles County Assessor

*P7. Owner and Address:
JAMES R & LARAIN E TRINITY
1629 GRANDVIEW AVE
GLENDALE CA 91201-1205

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1630 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1630 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-012

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style with French influence, constructed in 1941. It is irregular in plan with a hipped roof, clad in asphalt shingles. The walls are clad in wood-lap siding on the projecting front wing, and clad in smooth stucco with brick veneer on the lower portion of the façade on remainder of the house. The primary façade is asymmetrical. The windows are primarily divided-light casement constructed of steel. Character-defining features are series of asymmetrically interlocking hipped roofs, dominant chimney attached to front of projecting front wing composed of stones and brick, tall and narrow window frames on façade, diamond-paned leaded window panes on front wing, birdhouse atop roof ridge, and entryway defined by small porch with roof extension and wood posts with diagonal braces. Sole alteration visible from the street is a wood trellis at the north interior yard. Landscaping is dominated by a mature spruce in the front lawn. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1941
Los Angeles County Assessor

*P7. Owner and Address:
OH SANG H&JAE Y
1630 GRANDVIEW AVE
GLENDALE CA 91201-1262

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/2/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

**State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD**

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1631 Grandview Ave.

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

***a. County** Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

***b. USGS 7.5' Quad** Burbank **Date** 1972 **T** _____ ; **R** _____ ; **1/4 of** _____ **1/4 of Sec** _____ ; **B.M.** _____

c. Address 1631 Grandview Ave. **City** Glendale **Zip** 91201

d. UTM: (Give more than one for large and/or linear resources) **Zone** _____, _____ **mE/** _____ **mN**

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-002-002

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This single-family property was designed in the American Colonial Revival style and constructed in 1938. The one-story building is configured in a rectangular plan. The exterior cladding is smooth stucco with brick veneer on the lower portion of front façade. The side gable roof is clad with asphalt shingles and features include three gabled dormers. The offset entry features decorative wood trim. A three-sided bay is centered on the front façade. Windows are fixed and sliding, constructed of vinyl. Alterations include: installation of vinyl windows; removal of wood shingle cladding and its replacement with stucco; and the removal of decorative shutters. These changes have removed character-defining features of the original style. The overall integrity of this building is poor.

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____

7/6/2011

***P6. Date Constructed/Age and Source:** Historic Prehistoric Both

1938

Los Angeles County Assessor

***P7. Owner and Address:**

YESAY E & MARINE BAYASLYAN

1631 GRANDVIEW AVE

GLENDALE CA 91201-1205

***P8. Recorded by:** (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

***P9. Date Recorded:** _____

8/9/2011

***P10. Survey Type:** (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

***P11. Report Citation:** (Cite survey report and other sources, or enter "none.") None

***Attachments:** NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1635 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1635 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-002-001

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence, constructed in 1940 and designed in the Minimal Traditional style. Rectangular in plan, the house has a hipped roof, clad in shingles and smooth stucco walls. The facade is asymmetrical. The house features wood casement windows and vinyl horizontal slider windows, as well as a front entryway with a four-panel wood door with lights set at an angle to the front elevation. The character-defining features are the rounded corners, the prominent stone veneer chimney, the narrow tri-paned casement windows, the minimal, diagonal portico/entry porch with curved stone steps, and the partial stone base on the front elevation matching the exposed stone chimney. Alterations include the installation of vinyl windows and a change to the size of windows openings and the addition of stone veneer on chimney and steps. The overall integrity of the residence is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1940
City of Glendale Building Permit Records

*P7. Owner and Address:
ANDRE SAROUGHIAN
1635 GRANDVIEW AVE
GLENDALE CA 91201-1205

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

**State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD**

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1636 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M.

c. Address 1636 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-024

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a partial one- and two-story single-family residence designed with elements of Minimal Traditional and Monterey styles, constructed in 1938. It is rectangular in plan with a cross-gabled roof, clad in asphalt shingles. The walls are clad in smooth stucco with accents of wood-lap siding. The primary façade is asymmetrical. The windows are primarily double-hung with two smaller fixed windows, all of vinyl; the door is a six-paned wood door. Character-defining features are projecting three-sided bay window dominating front wing façade, decorative wooden shutters, horizontal wood-lap highlighting the front gable, with three triangular vents, small cantilevered balcony, with wooden beams and decorative wood balustrade, and small recessed stained glass window adjacent to front. Alterations include new vinyl windows set in existing openings, trellis porte-cochere, solar panels on roof, and side addition in 1952. Landscaping consists of curved concrete pathway and steps leading from driveway to front door. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1938
City of Glendale Building Permit Records

*P7. Owner and Address:
SAFAR I GHAZAL
1636 GRANDVIEW AVE
GLENDALE CA 91201-1262

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/2/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2 *Resource Name or # (Assigned by recorder) 1641 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T ____ ; R ____ ; 1/4 of ____ 1/4 of Sec ____ ; ____ B.M.

c. Address 1641 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone ____, ____ mE/ ____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-002-013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-and-a-half-story single-family residence was constructed in 1922 and designed in the American Colonial Revival style with elements of the French Eclectic and Dutch Colonial styles. Rectangular in plan, the house features a side-gambrel roof with flared eaves, clad in asphalt shingles, and smooth stucco walls. The facade is symmetrical. The windows are casement and divided-light, constructed of wood, with wall dormers with arched and broken pediments above the second floor windows, and hoods with corbels over the first-story windows. The central front entryway has a eight-panel wood door with sidelights and transom, framed by an open porch with classical columns and topped with by a second floor balcony with balustrade. The character-defining features consist of the window and door decorative treatments, and flared eaves. Alterations include a second-story addition above the one-story south side portion of the original structure and a two-story addition to the north side of the original structure.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1922
City of Glendale Building Permit Records

*P7. Owner and Address:
ERNEST G & JOAN M WILLIAMS
1641 GRANDVIEW AVE
GLENDALE CA 91201-1205

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1644 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T ___ ; R ___ ; 1/4 of ___ 1/4 of Sec ___ ; ___ B.M.

c. Address 1644 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone __, ___ mE/ ___ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-001

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence, formerly in the Monterey Revival style, that underwent an extensive remodel/new construction in the Neo-Colonial Revival style in 2008. It is rectangular in plan with a hipped roof and multiple gabled dormers, clad in asphalt shingles, and two balconies. The walls are clad in wood-lap. The primary façade is symmetrical. The windows are primarily double-hung divided-lights. Landscaping consists of mature spruce on property.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
City of Glendale Building Permit Records

*P7. Owner and Address:
BAGHDO & HERA FAM AKAY TRUST
221 W KENNETH RD
GLENDALE CA 91202

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/2/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1650 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1650 Grandview Ave. _____ City Glendale Zip 91201
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-001-002

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Craftsman style, constructed in 1927. Heavy landscaping and a large setback preclude significant public right-of-way observations of the dwelling. The low-pitched cross-gable roof is clad in composition shingles. Character-defining features are a substantial front porch, exposed rafter tails and projecting roof beams, and half-height square wood post set on masonry piers. Landscaping consists of a variety of shrubs and trees and a stone wall that outlines the front property line. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1927
City of Glendale Building Permit Records

*P7. Owner and Address:
KARAM & AMAL F RAYAD
1650 GRANDVIEW AVE
GLENDALE CA 91201-1262

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/2/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

**State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD**

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1655 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 1655 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-002-014

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence, constructed in 1949 and designed in the Ranch style. Rectangular in plan, the house features a low-pitch multi-gabled, wood shingle roof and an exterior clad in brick veneer. The primary façade is asymmetrical. The windows types are casement and divided-light, constructed of wood; the double door is beneath shallow shed roof. The character-defining features include an arched brick surround above window, a vented cupola with decorative hip roof, circular driveway, and interior brick chimney. Alterations include a two foot expansion of the living room and brick veneer finish added in 1990 and a new contemporary style door (wood with glass oval). Landscaping consists of well tended planters (clad in brick), bronze sculptures integrated into the front yard landscaping, and fence with brick piers and metal balustrade. The overall integrity of the original building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1949
City of Glendale Building Permit Records

*P7. Owner and Address:
JOHN J & SARALYNN GERAGHTY TR
1655 GRANDVIEW AVE
GLENDALE CA 91201-1205

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1658 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 1658 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-003

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style with French influence, constructed in 1939. It is L-shaped in plan with a steeply-pitched hipped roof, clad in asphalt shingles. The walls are clad in wood shingle on the main portion of the dwelling, and smooth stucco on the attached garage. The primary façade is asymmetrical. The windows are primarily divided-light fixed and casement windows constructed of steel, with several horizontal sliding windows, constructed of vinyl; the wooden door is situated perpendicular to Grandview. Character-defining features are front door with leaded glass light, bay window on side of house, with divided-light fixed panes, decorative wooden shutters, and brick chimney. Alterations include installation of vinyl windows on the side of house and a porch enclosure in 1984. Landscaping consists of curved brick pathway leading from sidewalk to primary door and several trees. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1939
City of Glendale Building Permit Records

*P7. Owner and Address:
ALAN R & CATHERINE M STEEL
1658 GRANDVIEW AVE
GLENDALE CA 91201-1262

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/2/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1661 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1661 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-001-001

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story single-family residence was constructed in 1936 and designed with eclectic stylistic features with an American Colonial Revival style influence. Rectangular in plan, the house features a hip roof, clad in asphalt shingles, and smooth stucco walls. The primary facade is symmetrical, with a central entryway featuring a pediment above the door with a leaded glass panel and sidelights. The windows are casement, divided-light and French doors, constructed of wood. The character-defining features include octagonal leaded glass windows, French doors flanked by wood shutters, metal balustrades on upper-story balconies, two brick piers frame the open porch and pedestal lights at the front entryway, brick chimney, and entrance framed by two pairs of two-story pilasters. The landscaping consists of manicured shrubbery and front lawn. The overall integrity of the house is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
PAGLIUSO JAMES J CO TR
1661 GRANDVIEW AVE
GLENDALE CA 91201-1205

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 2 *Resource Name or # (Assigned by recorder) 1663 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1663 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-001-002

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This two-story single-family residence was constructed in 1925 and designed in the Mediterranean Revival style. Rectangular in plan, the house features a low-pitch hip roof, which is clad in clay tile, and smooth stucco walls. The facade is asymmetrical. The windows types include arched, casement, double-hung, fixed and divided-light, all constructed of wood. The arched door is within projecting porch. The character-defining features of the residence are an integrated Porte Cochere with arched openings, low-pitch hip tile roof, arched openings, stucco wall cladding, picture windows on first story, projecting one-story porch with balcony and multiple arched openings, wrought iron balustrade on windows and balcony, and pronounced eave brackets. Alterations include a two-story addition to the rear and change-out of all doors and windows for the entire house in September 2000. The landscaping features manicured hedges and shrubs, rose bushes along the driveway, and a mature cypress tree. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
City of Glendale Building Permit Records

*P7. Owner and Address:
DAVIS TRUST
1663 GRANDVIEW AVE
GLENDALE CA 91201-1205

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1700 Grandview Ave.

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

***a. County** Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

***b. USGS 7.5' Quad** Burbank **Date** 1972 **T** _____ ; **R** _____ ; **1/4 of** _____ **1/4 of Sec** _____ ; **B.M.** _____

c. Address 1700 Grandview Ave. **City** Glendale **Zip** 91201

d. UTM: (Give more than one for large and/or linear resources) **Zone** _____ **mE/** _____ **mN** _____

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-034

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence originally designed in the American Colonial Revival style with Dutch Colonial Revival influence, now dramatically altered. It was constructed in 1913 by L.C. Brand for his niece Ada Dryden Thompson. The residence is locally referred to as the Thompson/Armstrong House for its association with Ada Dryden Thompson and Charlotte Armstrong, a well-known author, who lived in the residence. It is irregular in plan with a gambrel roof, clad asphalt shingle. The walls are clad in smooth stucco. The windows are single pane casement and fixed with some divided-light windows on the first floor. The wood paneled door features sidelights. Character-defining features include gambrel roof, covered porch and shed dormers. Alterations include reroof replacing clay tile roof with asphalt shingle, and the replacement of windows and re-stuccoing of exterior walls in 1989. The porch appears to be altered. Landscaping consists of curved concrete driveway, lawn, fan palms and large fir trees. The overall integrity of this building is fair.

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

***P6. Date Constructed/Age and Source:** Historic Prehistoric
 Both

1913
Los Angeles County Assessor

***P7. Owner and Address:**
ASHOD K & VREJOUHY O PAPELIAN
1700 GRANDVIEW AVE
GLENDALE CA 91201-1208

***P8. Recorded by:** (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

***P9. Date Recorded:** _____
8/8/2011

***P10. Survey Type:** (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

***P11. Report Citation:** (Cite survey report and other sources, or enter "none.") None

***Attachments:** NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1701 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1701 Grandview Ave. _____ City Glendale Zip 91201
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5622-001-003

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one and a half story single-family residence was constructed in 1937 and designed in the Minimal Traditional style. Irregular in plan, the house features a hip roof, clad in composition shingles, and walls clad in stucco with accents of wood-lap and brick. The facade is asymmetrical, with double-hung, fixed and divided-light windows and a front door with sidelights. The character-defining features include gabled roof dormers, two projecting three-sided bay windows with brick cladding, gabled wall dormers above projecting bay windows, and circular driveway. Alterations include re-roof (composition shingles over wood shingles) in 1981. The landscaping features numerous mature trees and multiple birch saplings planted in the front lawn. The overall integrity of this residence is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1937
City of Glendale Building Permit Records

*P7. Owner and Address:
CONAN P NOLAN
1701 GRANDVIEW AVE
GLENDALE CA 91201-1207

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1707 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1707 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-001-004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence, constructed in 1923 and designed in the Craftsman style. Irregular in plan, the structure features a low-pitch multiple gable roof, clad in composition shingles, and rough stucco walls. The primary façade is asymmetrical, with a front porch recessed beneath front-facing gable roof. The windows are casement and fixed divided-light, constructed of wood. The character-defining features include several brick chimneys, decorative gable vents, protruding roof beams, and fixed shutters. Alterations include a new wing (two bedrooms and two baths) added to the north side of the residence in 1988, wall cladding, and porch. Landscaping consists of numerous mature trees throughout the site, as well as manicured hedges along the front elevation. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1923
City of Glendale Building Permit Records

*P7. Owner and Address:
GEORGE C JR MCCULLOUGH TR
1707 GRANDVIEW AVE
GLENDALE CA 91201-1207

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1708 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1708 Grandview Ave. City Glendale Zip 91201
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-005-033

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one and a half story single-family residence designed in the Minimal Traditional style, built in 1939. It is square in plan with steeply-pitched hip roof with a gable roof over the front facing garage all clad in asphalt shingles. The primary façade is asymmetrical. The walls are clad with smooth stucco with a low brick wainscot veneer across the primary facade. The windows are fixed and casement, constructed of vinyl. There are fan lights above the primary entry and garage door and a large projecting three-sided bay picture window is in the center of the façade. It contains a central single-light fixed window flanked by divided-light casement windows. A gable arch defines the main entry porch. Character-defining features include gable roof dormers, a steeply-pitched roof, and projecting bay window. The building was originally permitted as a one-story residence and although no permits are on file the build appears to have been altered to include the half story, roof dormers and covered main entry. New vinyl windows have also been installed. Landscaping consists of concrete driveway brick detailing, curved brick walkway to porch, lawn, and low brick planters. The overall integrity of this building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1939
City of Glendale Building Permit Records

*P7. Owner and Address:
MATUOS & MICHELLE MATTI TR
1708 GRANDVIEW AVE
GLENDALE CA 91201-1208

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

**State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD**

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1714 Grandview Ave.

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1714 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-008

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1934. It is irregular in plan with a gable roof and front facing gable end clad in asphalt shingles. The primary façade is asymmetrical. The walls are clad in brick with accents of vertical wood board and batten and horizontal wood-lap siding in the front facing gable ends. The windows are vinyl with internal grids. The main entry features a minimal porch supported by square columns and include a brick porch and four paneled double wood doors. Alterations include the addition of a den in 1950, contemporary door and walkway, and new driveway. Landscaping consists of tall birch and Sycamore trees, planter areas with brick walkway, and lawn. The overall integrity of this building is good.

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

***P6. Date Constructed/Age and Source:** Historic Prehistoric
 Both

1934
Los Angeles County Assessor

***P7. Owner and Address:**
HAROLD R & JEAN J GINDER
1714 GRANDVIEW AVE
GLENDALE CA 91201-1208

***P8. Recorded by:** (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

***P9. Date Recorded:** _____
6/14/2011

***P10. Survey Type:** (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

***P11. Report Citation:** (Cite survey report and other sources, or enter "none.") None

***Attachments:** NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1717 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M.

c. Address 1717 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-001-005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story single-family residence was constructed in 1922 with elements of the Craftsman style. Rectangular in plan, the house features a low-pitch multiple gable roof, clad in asphalt shingles, and wood-lap exterior walls. The primary facade is asymmetrical. The types of windows include original double-hung and fixed divided-light wood windows, and new aluminum horizontal sliders; the door is constructed of wood. The character-defining features include tripartite windows with fixed divided-light transoms flanked by two double-hung windows, low-pitch gable roof, wood-lap cladding, and protruding roof beams and exposed rafter tails. Permitted alterations include an entrance room added in 1971 and a residential addition (break room, laundry, bath and porte cochere) constructed in 2000, the decorative (sunbursts) gable vents may date to this work. Landscaping consists of a front lawn, a few bushes directly adjacent to the front elevation, and mature palms next to the sidewalk. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1922
City of Glendale Building Permit Records

*P7. Owner and Address:
B EUGENE & JAMIE D REEVES
1717 GRANDVIEW AVE
GLENDALE CA 91201-1207

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1720 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1720 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1936. It is irregular in shape with a low-pitch gable roof and front facing gable end all clad in concrete tile. The primary façade is asymmetrical. The walls are clad with brick and have accents of wood in the gable ends. The windows are casement with divide lights constructed of metal. The porch is covered with a shed roof supported with square brick columns and features a wrought iron railing and a natural wood door. Alterations include enclosure of patio in 1949. Character-defining features include decorative wood shutters and scalloped horizontal siding in front facing gable end. Landscaping consists of lawn, mature trees, and various plantings bordering driveway and in planter areas near structure. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

<p>P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)</p> 	<p>P5b. Description of Photo: (view, date, accession #) _____ <u>7/6/2011</u></p> <p>*P6. Date Constructed/Age and Source: <input checked="" type="checkbox"/> Historic <input type="checkbox"/> Prehistoric <input type="checkbox"/> Both</p> <p><u>1936</u> City of Glendale Building Permit Records</p> <p>*P7. Owner and Address: <u>JOHN T & BETTY H MINNICK TR</u> <u>1720 GRANDVIEW AVE</u> <u>GLENDALE CA 91201-1208</u></p> <p>*P8. Recorded by: (Name, affiliation, and address) <u>Glendale Planning Division</u> <u>633 E. Broadway, Rm. 103</u> <u>Glendale, CA 91206</u></p> <p>*P9. Date Recorded: _____ <u>6/14/2011</u></p> <p>*P10. Survey Type: (Describe) <u>N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)</u></p>
--	--

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1725 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1725 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-001-006

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence, constructed in 1956 and designed in the Ranch style with Craftsman influences. Rectangular in plan, the house features a low-pitch side gable roof with front facing gable clad in composition shingles, and exterior walls covered in wood lap. Asymmetrical in facade, the house has casement and divided-light wood windows, a double front door under an arched recessed porch, and an attached one-car garage on the south side and an attached two-car garage on the north side. The character-defining features include corbels in gable and low-pitch roof. Alterations include brick porch, landing and piers, siding, and roof. The front yard features a circular driveway (with access on both sides to the one- and two-car garages) and mature trees (including palms). The overall integrity of the house is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1956
City of Glendale Building Permit Records

*P7. Owner and Address:
SHANT & A FAM HAMAMAH TRUST
1725 GRANDVIEW AVE
GLENDALE CA 91201-1207

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1729 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1729 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-001-007

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one- and a half-story single-family residence was constructed in 1922 and designed in the French Eclectic style. Rectangular in plan, the house features a steeply-pitched side-gable with hipped, shed and conical roofs, clad in asphalt shingles, and smooth stucco walls. The primary façade is asymmetrical, with a wood door framed by sidelights. The windows are casement and fixed divided-light, constructed of steel. The character-defining features include half-timbering, diamond paned leaded windows, weather above porch with brick landing turned spindle porch supports and conical roof, three-sided bay windows, brick elements (such as brick stairs, brick planters, brick chimney), and a Porte Cochere with a wrought iron decorative gate. Alterations include a new second floor addition to the north (right) of the existing residence with a Porte Cochere underneath leading to a new two-car garage (1981), new front entrance (1983), new shingle roof (2000). The landscaping consists of brick planters, statuary, and a circular driveway. The overall integrity of the residence is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1922
City of Glendale Building Permit Records

*P7. Owner and Address:
AKERS TRUST
1729 GRANDVIEW AVE
GLENDALE CA 91201-1207

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1730 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1730 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-024

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1936. It is irregular in plan with a cross-gable roof, clad in asphalt shingles. The walls are clad in rough stucco with accents of wood siding in gable ends. The primary façade is asymmetrical. The windows are combination of casement and fixed, with two projecting three-sided bay windows, constructed of wood; the six-panel door is constructed of wood. Character-defining features are minimal porch with decorative scrollwork and wrought iron railing. Landscaping consists of mature Chinese elm tree. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
MARCO ARRIETA
1730 GRANDVIEW AVE
GLENDALE CA 91201-1263

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1734 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1734 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-025

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed with elements of the English Tudor Revival style, constructed in 1935. It is irregular in plan with a multi-gabled roof, clad in faux wood shingles. The walls are clad in smooth stucco with accents of brick and half-timbering. The primary façade is asymmetrical. The windows are combination of casement divided-light, fixed and solid pane. Character-defining features are long covered porch, half-timbering, and corbel chimney. This residence has been altered by adding second story in 1983, windows, porch overhang, and side window pane with covered awning. Landscaping consists of mature Coast Live Oak in front lawn. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
City of Glendale Building Permit Records

*P7. Owner and Address:
LUCIEN & MARY M HERSH TRUSTEES
1734 GRANDVIEW AVE
GLENDALE CA 91201-1263

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1735 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1735 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-001-008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The is a two-story single-family residence constructed in 1999 and designed in the Neo-Mediterranean Revival style. Rectangular in plan, the house has a low-pitch clay tile hip roof and smooth stucco walls. The facade is mostly symmetrical, with a central front entryway with sidelight windows. The house has casement, fixed, divided-light (with semi-circular tops) windows, and French doors, either in wood or vinyl. The character-defining features are decorative metal balustrade on windows, stucco chimney, attached two-stall garage, and porch with round classical columns with clay tile clad shed roof and brick landing with metal balustrade. The landscaping consists of a circular driveway and numerous planted palms and bushes around a central front lawn. The overall integrity of this building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1999
City of Glendale Building Permit Records

*P7. Owner and Address:
ROMEL D & MERCEDES FERNANDEZ TR
1735 GRANDVIEW AVE
GLENDALE CA 91201-1207

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1740 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1740 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-026

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1935. It is irregular in plan with a low-pitch multi-gabled roof, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are combination of fixed, sliding-horizontal, single pane, and bay and appear to be constructed of vinyl. Character-defining features are the covered porch and chimney. This residence has been altered by adding two rooms and bath in 1975 and aluminum covered patio in 1962. Additionally, in 2006 stucco surrounds were added at the windows and wood siding under gables were removed. Landscaping consists of brick parkway. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
City of Glendale Building Permit Records

*P7. Owner and Address:
VASKEN & TAMAR KAYPEKIAN
1740 GRANDVIEW AVE
GLENDALE CA 91201-1263

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1745 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1745 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5622-001-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This one-story single-family residence was constructed in 1951 and designed in the Minimal Traditional style. Rectangular in plan, the house features a low-pitch hip roof, clad in asphalt shingles and smooth stucco walls. The facade is asymmetrical, with the inset porch and front door perpendicular to the street (facing the driveway). The windows are casement and fixed divided-light steel windows. The character-defining features are attached one-stall garage with hip roof, fixed shutters, original wrought iron porch railings and post, and a brick chimney. The landscaping is minimal. The overall integrity of the residence is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1951
City of Glendale Building Permit Records

*P7. Owner and Address:
DANE C NORMAN
1745 GRANDVIEW AVE
GLENDALE CA 91201-1207

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/9/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1746 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1746 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-029

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1935. It is rectangular in plan with a low-hipped roof, clad in fiberboard shingles. The walls are clad in smooth stucco with accents of vertical wood. The primary façade is asymmetrical. Vinyl windows are double-hung internal grid; door is single-panel and made of wood. Character defining features are inset porch, chimney, and shutters. This residence has been altered by the 1990 addition of a master bedroom and bathroom at the rear of the residence and 1986 addition of a wood screen to hide roof heating unit. Other alterations include the addition of stone wainscoting to the front right façade, replacement of original post porch supports with columns, and removal of all window shutters. Overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
City of Glendale Building Permit Records

*P7. Owner and Address:
JOSEPH NAZARI
1746 GRANDVIEW AVE
GLENDALE CA 91201-1263

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1750 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T ___ ; R ___ ; 1/4 of ___ 1/4 of Sec ___ ; ___ B.M.

c. Address 1750 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone ___, ___ mE/ ___ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-030

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family two-story residence designed in the Mediterranean Revival style, constructed in 1924. It is rectangular in plan with a combination multi-gabled and low hipped roof, with a shed feature all clad in non-original clay tile. The walls are clad in non-original rough stucco and the primary façade is asymmetrical. The windows are aluminum double-hung and sliding with internal grids; the front door is non-original with side-lights and recessed within the front gable entry porch with polygonal arch opening. Character-defining features are square shape portico and low-pitched tile roof. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1924
City of Glendale Building Permit Records

*P7. Owner and Address:
SHAHEN & TERESA VOSKANIAN
1750 GRANDVIEW AVE
GLENDALE CA 91201-1263

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1754 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; _____ B.M.
c. Address 1754 Grandview Ave. _____ City Glendale Zip 91201
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-004-033

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family two-story residence designed in the Neo-Spanish Colonial Revival style, constructed in 2005. Architectural features include walls clad with stucco; red clay tile roof, round two-story turret at entry, and parabolic picture window at projecting one-story wing.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/6/2011.

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

2005

*P7. Owner and Address:

VARTAN VARTANIANS
1754 GRANDVIEW AVE
GLENDALE CA 91201-1263

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1760 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1760 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-034

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1950. It is L-shaped in plan with a medium, multi-hipped roof, clad in asphalt-shingles. The walls are clad in wood with stone accents on lower portion of façade. The primary façade is asymmetrical. The windows are casement and fixed, constructed of steel; the single door is covered by a wide projecting shed roof porch with wood turned spindles. Character-defining features include metal railings, extended porch with support posts, and a decorative brick chimney. Landscaping consists of mature sycamore trees in front. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1950
City of Glendale Building Permit Records

*P7. Owner and Address:
CAROLYN J DITTMER TRUST
1760 GRANDVIEW AVE
GLENDALE CA 91201-1263

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5B

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 3 *Resource Name or # (Assigned by recorder) 1770 Grandview Ave.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1770 Grandview Ave. City Glendale Zip 91201

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-003-011

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two- and three-story single-family residence on a corner lot designed in the Spanish Colonial Revival style and constructed in 1925. It is irregular in plan with a multiple gabled roof, clad in clay tile and flat roof with parapet at the rear. The walls are clad in stucco. The façade is asymmetrical. The windows are casement divided-light constructed of wood; the door is wood, multi-paneled and semicircular with a stepped radiating cast stone surround; a glass and metal curved hood is above the front door. Character-defining features are an exterior courtyard, arcade porch support, decorative vents, wide porch with multiple arched openings, three-story tower with hip roof and round turret, parapet on the second floor balcony, low relief ornamentation on second story, a balustrade on one side/third story, wing wall, ornamentation consisting of a decorated frieze on the bottom portion of the turret, open (See Continuation Sheet)

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
City of Glendale Building Permit Records

*P7. Owner and Address:
ROBIK & CARMEN I OVANESIAN
PO BOX 271
GLENDALE CA 91209

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1714 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1714 Idlewood Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-008

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1925. It is rectangular in plan with a flat roof with a clay tile-clad parapet. The walls are clad in rough stucco. The primary façade is asymmetrical. The windows are double-hung and fixed, divided-light type, constructed of wood. Character-defining features include wide arched porch with tile-clad shed roof, tripartite windows with small panes on upper portion, and an arched molding above window. Alterations include stucco cladding, canvas awning above tripartite windows, and wrought-iron vent cover. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
City of Glendale Building Permit Records

*P7. Owner and Address:
SHIRLEY E PETRAITIS TR
1714 IDLEWOOD RD
GLENDALE CA 91202-1030

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1717 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1717 Idlewood Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-015

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence originally designed in the Minimal Traditional style, constructed in 1937. It was dramatically remodeled in 2009 in a Neo-Spanish Colonial style.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1937
City of Glendale Building Permit Records

*P7. Owner and Address:
HAROUT & VICKY ODABACHIAN
1717 IDLEWOOD RD
GLENDALE CA 91202-1029

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1720 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1720 Idlewood Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1935. It is L-shape in plan with a low-pitch gabled roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are fixed divided-light, arched, and projecting, three-sided bay type, constructed of wood; the arched wood door is recessed. Character-defining features include exposed rafter tails, carved wood and decorative accents in the glass of small front bay window, square entry tower with clay tile-clad hip roof and grille above the door, molded entry, and wrought iron vent covers. A front courtyard of fairly recent vintage was added at an unknown date. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
City of Glendale Building Permit Records

*P7. Owner and Address:
ASHOD & JOAN KARGODORIAN
1720 IDLEWOOD RD
GLENDALE CA 91202-1030

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1721 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1721 Idlewood Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-014

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1937. It is L-shaped in plan with a low-pitch hipped roof on the central block and front gabled roof on the front wing, all clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. All windows are constructed of vinyl; the door is non-original. Character-defining features are attached two-stall garage and a chimney located in the center of the house. Alterations include contemporary garage door, new cement brick driveway, installation of double-hung vinyl windows, and removal of garage dovecote. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1937
City of Glendale Building Permit Records

*P7. Owner and Address:
LEVON & GOHAR M GRBOYAN
1721 IDLEWOOD RD
GLENDALE CA 91202-1029

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1722 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1722 Idlewood Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-010

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1930. It is L-shaped in plan with a low-pitch front and side gable roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are double-hung, fixed, divided-light and constructed of wood. The door is recessed within the porch. Character-defining features include large arched picture windows, large inset arched porch, small recessed windows on second floor, projecting balcony with metal balustrade, exposed rafter tails. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1930
City of Glendale Building Permit Records

*P7. Owner and Address:
KEN K OKUYAMA
1722 IDLEWOOD RD
GLENDALE CA 91202-1030

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1725 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1725 Idlewood Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the American Colonial Revival style, constructed in 1938. It is rectangular in plan with a steeply-pitched hipped roof on the central block, and multiple front gabled wings, all clad in asphalt shingles. The walls are clad in smooth stucco with accents of stone and wood siding. The primary façade is asymmetrical. The windows are primarily divided-lights, either fixed or casement, constructed of steel, augmented by a fixed single pane projecting three-sided bay with diamond panes. Character-defining features are half-timbering, recessed entry porch, varying eave lines, wrought iron posts framing the entranceway, steeply-pitched dormer on side of house, decorative shutters, and a variety of exterior cladding materials including stone, and stucco. Alterations include installation of aluminum windows and installation of exterior wall cladding. Landscaping consists of a mature tree in the front lawn accompanied with a variety of shrubs. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1938
City of Glendale Building Permit Records

*P7. Owner and Address:
GLEND A BOLLER TR
1725 IDLEWOOD RD
GLENDALE CA 91202-1029

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1728 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1728 Idlewood Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-003-011

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1935. It is L-shaped in plan with a low gable roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are casement divided-light constructed of wood. Character-defining features include the arched corbels under the second story, covered side fate entry, round tower over entry, picture window of leaded glass, Living room ceiling sloped sway from house, large arched covered porch, exposed rafter tails, wrought iron railings. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
City of Glendale Building Permit Records

*P7. Owner and Address:
VERNON L & DIANE C PRUETT
1728 IDLEWOOD RD
GLENDALE CA 91202-1030

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

**State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD**

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1729 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M.

c. Address 1729 Idlewood Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-012

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1949. It is square in plan with a low-pitch hipped roof, clad in asphalt shingles. The walls are clad in smooth stucco with stone accents on lower portion of façade. The primary façade is asymmetrical. The newer replacement windows are primarily double- or single-hung, vinyl with internal grids; the door is located on the central block façade, adjacent to the front wing. Character-defining features are fixed shutters, recessed entry porch defined by slender wood posts and metal railing, picture window with extended roof line as awning, multiple roof line defined by main hipped roof and two more defined hipped segments, and red brick chimney attached to the side of the house. Alterations include installation stone veneer cladding at the base. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/26/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1949
City of Glendale Building Permit Records

*P7. Owner and Address:
GELINDO & ANGELINA MARRONE TR
1729 IDLEWOOD RD
GLENDALE CA 91202-1029

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1734 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1734 Idlewood Rd. _____ City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5629-003-012

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence, on a corner lot with two street façades, designed in the Spanish Colonial Revival style, constructed in 1930. It is L-shaped in plan with a low-pitched gabled and shed roofs clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are fixed and casement divided-light windows, some of which are arched constructed of wood. Character-defining features include projecting balcony with tile roof and wood balustrades and supports, corbels beneath overhanging second story, eave brackets, exposed rafter tails, wrought iron railings, recessed arched picture window with protruding sill, arcade porch with shed roof, exterior courtyard enclosed by low stucco wall, and French doors to patio. Alterations include the installation of canvas awnings. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1930
City of Glendale Building Permit Records

*P7. Owner and Address:
ROBERT E & ROBIN T JOHNSON
1734 IDLEWOOD RD
GLENDALE CA 91202-1030

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1735 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1735 Idlewood Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-002-011

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the French Eclectic style, constructed in 1924. It is L-shaped in plan with a primarily hipped roof with a prominent front facing gable, all clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are divided-light casements constructed of wood and aluminum sliding at side façade; single-panel door featuring three vertical lights is constructed of wood. Character-defining features are wide brick chimney prominently situated in the center façade of the central block, brick trim window sills, decorative wood shutters, and a steeply-pitched hipped roof. Alterations include installation of metal awning attached to shed roof over the main entry. Landscaping consists of large planter with multitude of flowers and shrubs partially defining the pathway to the entrance and mature tree dominating the front lawn. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1924
City of Glendale Building Permit Records

*P7. Owner and Address:
MIKAL & HELEN GERRICK TR
1735 IDLEWOOD RD
GLENDALE CA 91202-1029

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 5/26/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1805 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1805 Idlewood Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-018

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style with French Eclectic elements constructed in 1940. It is rectangular in plan with a hip roof, clad in wood shingles, small boxed cornices and small arched roof dormers with louvers. The primary facade is asymmetrical. The walls are clad in stucco with accents of wood. Windows consist of six-over-six divided-light double-hung sash windows, a three-sided bay window with diamond pane covered by projecting copper canopy on the southern elevation, and a similar bay with fixed pane on facade. The main entry features a projecting arched pediment with architrave trim, molded cornice and fascia with fluted pilasters and a recessed two paneled door with side by side arched elaborated leaded glazed lights. Character-defining features include diamond pane glass, decorative details around the doors and windows, roof vents, arched pediment above main entry and projecting bays. Alterations include some replacements of windows. Landscaping consists of low planter beds near exterior with Bird of Paradise, dracaena, camellias and formal planting, and lawn. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1940
City of Glendale Building Permit Records

*P7. Owner and Address:
PHILIP J LOGA
1805 IDLEWOOD RD
GLENDALE CA 91202-1031

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1815 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1815 Idlewood Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-019

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1931. It is T-shape in plan with a hip roof and front-facing gable end clad in Spanish red clay tile. The primary façade is asymmetrical. The walls are clad with smooth stucco. The wood windows are casement and fixed constructed of wood and feature a pointed arch picture window on the front facing gable end. Portions of the arched windows are stained leaded glass. The main entry features an exterior courtyard enclosed by a half height wall and a covered porch with a trio of arched openings. Character-defining features include leaded stain glass, decorative iron work, a wing wall with an arched opening, a Porte Cochere, and a decorative wrought iron gate that opens to the exterior courtyard. Landscaping consists of the lawn, various plantings, a low brick planter with rose garden, a curved driveway paved with brick, and curved brick walkway leading to the main entry. The overall integrity of this building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1931
City of Glendale Building Permit Records

*P7. Owner and Address:
JAMES M & EILEEN H GIVENS TR
1815 IDLEWOOD RD
GLENDALE CA 91202-1031

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1820 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____
c. Address 1820 Idlewood Rd. _____ City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-006-031

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Ranch style with Modern influences, constructed in 1956. It is irregular in plan with a low-pitched hip roof with overhanging eaves, clad in gravel. The walls are clad in smooth stucco with accents of stone veneer. The primary façade is asymmetrical. The windows are single pane casement constructed of steel. Character-defining features include the low profile of the design, the large overhanging eaves and rock faced entry and chimney. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1956
City of Glendale Building Permit Records

*P7. Owner and Address:
VINCENT L ZARIAN
1820 IDLEWOOD RD
GLENDALE CA 91202-1032

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1821 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1821 Idlewood Rd. _____ City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-005-020

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1953. It is L-shaped with a hip roof, clad in asphalt shingles. The primary façade is asymmetrical. The walls are primarily clad with rough stucco but there is vertical board-and-batten siding on the garage elevation and wood shingles on the facade. In the center of the façade there is a recessed porch. Character-defining features include attached garage, chimney, wood shingle cladding, and vertical wood board-and-batten siding. Alterations include minor extension of the roof over the rear porch in 1958, bedroom addition at rear of the residence in 1983, installation of new vinyl sliding windows and decorative column at recessed porch. Landscaping consist of small lawn area and flower beds adjacent to driveway. The overall integrity of this building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1953
City of Glendale Building Permit Records

*P7. Owner and Address:
EDMOND ARUTYUNYAN
333 E GLENOAKS BLVD 100
GLENDAL CA 91207-2074

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1829 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1829 Idlewood Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-024

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story with partial two-story single-family residence designed in the Ranch style, constructed in 1948. It is rectangular in plan with a side gable roof and front facing gable end all clad in concrete shingles. The primary façade is asymmetrical, with a carport near the center of the façade. The walls are clad with horizontal wood-lap and smooth stucco with vertical wood board siding on the front facing gable end. The windows are casement, fixed and double-hung divided lights constructed of wood and vinyl. A second-story addition added in 1958 is at odds with the Ranch style, making this property a non-contributing structure. Other alterations include the addition of a metal awning above the window on the front-facing gable end. Character-defining features include the car port near the center of the facade, front-facing gable end, and series of three casement windows on the northern portion of the façade. Landscape includes lawn and manicured planting areas of assorted low bushes next to structure. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1948
City of Glendale Building Permit Records

*P7. Owner and Address:
WILLIAM F & MARY H MULLEN TR
1829 IDLEWOOD RD
GLENDALE CA 91202-1031

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1830 Idlewood Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1830 Idlewood Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-006-032

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story, split-level single-family residence designed in the Ranch style, constructed in 1965. It is rectangular in plan with a gable-on-hip roof, clad in asphalt material. The walls are clad in smooth stucco with accents of wood and brick. The primary façade is asymmetrical. The windows are wood casement divided-light. Stairs with a metal balustrade lead to the main entry. Character-defining features include multiple types and sizes of wood panel windows, brick accents on retailing walls, entry, porch and walls, vertical wood cladding, fixed wood shutters. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1965
Los Angeles County Assessor

*P7. Owner and Address:
AJABI FAMILY TRUST
1830 IDLEWOOD RD
GLENDALE CA 91202-1032

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 850 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 850 Matilija Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-004-009

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1928 on a lot with three street frontages. It is irregular in plan with a low-pitched gabled roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are divided-light casement styles constructed of wood. A canvas awning covers a second-story set of French doors. The side yard is enclosed by an attached stucco-clad wall. The property has a two-car garage with stucco cladding and a tile roof. Character-defining features include multiple balconies with wood supports and balustrades and shed tile-clad roofs, exposed rafter tails, corbels beneath projecting balconies, wrought iron grilles on windows, decorative tile around the entrance, and tapered stucco chimneys. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
8/31/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1928
City of Glendale Building Permit Records

*P7. Owner and Address:
GARY S & DEANNE H GOODMAN
850 MATILIJA RD
GLENDALE CA 91202-1033

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 855 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 855 Matilija Rd. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-006-029

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence originally designed in the Spanish Colonial Revival style, constructed in 1925. It is rectangular in plan with a front and side-gable roof, clad in clay tile. The walls are clad in smooth stucco with accents of wood-lap in the gable end. The primary façade is asymmetrical with a covered porch. The windows are single pane, fixed and louvered styles constructed of wood. Character-defining features include inset porch with low stucco wall and wood posts and recessed door within porch. Alterations include wood siding in the gable and change to windows in 1958. Landscaping consists of mature trees, lawn and various plantings. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925
Los Angeles County Assessor

*P7. Owner and Address:
JEFFREY Y & LETICIA S SOOHOO
855 MATILIJIA RD
GLENDALE CA 91202-1057

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 863 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 863 Matilija Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-006-028

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the English Tudor Revival style, constructed in 1927. It is L-shaped in plan with a steeply-pitched, side gable roof with two prominent front-facing gables, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows include fixed, louvered, single pane and rounded-arch types constructed of wood and steel. Character-defining features include wrap-around eaves along front gables, large semi-elliptical arched roofline in center of the facade, large three arched tripartite Palladian-style window with some surrounds. Alterations include the installation of aluminum windows on the western and center portion of the façade, and the attached, stucco-clad wall. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1927

Los Angeles County Assessor

*P7. Owner and Address:

KARAPET & VARDUI L EDINCHIKYAN

863 MATILIJA RD

GLENDALE CA 91202-1057

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

8/5/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 869 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T ___ ; R ___ ; 1/4 of ___ 1/4 of Sec ___ ; B.M.

c. Address 869 Matilija Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone __, ___ mE/ ___ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-006-027

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-and-one-half story, single-family residence designed with elements of the Minimal Traditional style, constructed in 1941. It is L-shaped in plan with a steeply-pitched, side-gable roof, with a hipped roof in front, clad in asphalt shingles and a flat-roofed dormer. The walls are clad in rough stucco with vertical and paneled wood accents and a stone veneer. The primary façade is asymmetrical. The windows are divided-light, double-hung, and one projecting, 3-sided bay styles constructed of wood. The door is in a recessed entryway with porch featuring wood post and metal balustrade. Character-defining features include decorative shutters, one large bay window with diamond-patterned glass and molding along top and bottom, a protruding boxed window with half-timbering and corbels and flagstone accents under front window and porch. Alterations include two-story rear addition built in 1977 and a reconstructed chimney. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____

7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric Both

1941

City of Glendale Building Permit Records

*P7. Owner and Address:

ROBERT E & CAROL A BROWN

869 MATILIJA RD

GLENDALE CA 91202-1057

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

8/5/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 871 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 871 Matilija Rd. _____ City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-006-026

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Monterey Revival style, constructed in 1932. It is L-shaped in plan with a side-gable and shed roof, clad in asphalt shingles. The walls are clad in smooth stucco with accents of vertical wood and brick veneer, and wood-lap in side gable. The primary façade is asymmetrical. The windows are casement divided-light constructed of wood. Character-defining features include stucco chimney, inset second story balcony with wood posts and balustrade, fixed shutters, a Porte Cochere with shed roof and wood-lap siding, a set of French doors on projecting first story wing, decorative molding around front door with a crown above door, vertical wood slats in balcony along second story. Landscaping consists of mature hedges, ground cover, and wall with brick piers and stucco balustrade. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1932
City of Glendale Building Permit Records

*P7. Owner and Address:
CHRISTOPHER S & LINDA L LOWERY
871 MATILIJA RD
GLENDALE CA 91202-1057

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 877 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 877 Matilija Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-006-025

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1936. It is L-shaped in plan with a low-pitch side-gable roof with one-story front-gabled wing, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are predominately divided-light, casement constructed of wood with an arched picture window with leaded divided-light. Character-defining features include arched recessed leaded glass window, exposed rafter tails, arched entry, multiple arches around front projecting arcaded porch with tile clad roof, arched wing wall with tile cladding and arched opening, and Porte Cochere with tile roof and arched opening. Alterations include a bedroom addition in 1965 and the addition of canvas awnings. Landscaping consists of mature palm trees, lawn, and various plantings. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936
City of Glendale Building Permit Records

*P7. Owner and Address:
ARMANDO & CATHERINE T BERRIZ
877 MATILIJA RD
GLENDALE CA 91202-1057

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 881 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 881 Matilija Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-006-024

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style with Mediterranean Revival influences, constructed in 1932. It is irregular in plan with a low-pitched hip roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical with an exterior courtyard. The windows are divided-light and casement constructed of wood. Character-defining features include a small stained glass oval window over door, exposed rafter tails, string course between floors, French doors, balconies, iron balustrade on windows and French double doors and around exterior courtyard, molded stone surrounding front door, and brick accent trim under front window and fireplace. The front façade is largely covered with vegetation. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1932
Los Angeles County Assessor

*P7. Owner and Address:
STEPHEN O PLACIAL TRUST
881 MATILIJIA RD
GLENDALÉ CA 91202-1057

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 889 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 889 Matilija Rd. _____ City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-006-023

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1932. It is L-shaped in plan with a low-pitch side-gable roof, clad in clay tile. The walls are clad in smooth stucco. The primary façade is asymmetrical. The windows are divided-light, casement including an arched picture window constructed of wood. Character-defining features include a large arched picture glass window, decorative fixed wood shutters, exposed rafter tails, string course delineating upper and lower story, corbels beneath overhanging second story, decorative windows on side, and French doors to two balconies. Alterations include backyard addition, and new molding around entry and arched picture window. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1932
City of Glendale Building Permit Records

*P7. Owner and Address:
PHILIP F & JOANN KENNEY
889 MATILIJIA RD
GLENDALE CA 91202-1057

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 909 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 909 Matilija Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-017

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1931. It is irregular in plan with a low-pitched roof and features a round tower that rises above the roofline all clad in clay tile. The primary façade is asymmetrical. The walls are clad with smooth stucco. The windows are casement divided-light and single pane and constructed of wood. Door is original heavy wood of a distressed Spanish style with brick sill. Character-defining features include recessed windows with sills made of brick, exposed rafter tails, entry portico with arched opening within tower with brick steps forming the main entry, chimney flush with primary façade and metal top, and a Porte Cochere with double wooden scalloped stick style gate. Landscape includes small curved walkway from driveway to vine covered entry, lawn, beds of flax, Bird of Paradise, and annual flowers. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1931

Los Angeles County Assessor

*P7. Owner and Address:

JEROME P & GLORIA W SANDER

909 MATILIJIA RD

GLENDALE CA 91202-1034

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

2/10/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 913 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 913 Matilija Rd. _____ City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-005-028

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style with French Eclectic influence, constructed in 1941. It is slightly L-shaped in plan with a medium pitch hipped roof, clad in asphalt shingles. The primary façade is asymmetrical. The walls are clad in smooth stucco with a brick veneer on the western portion of the facade. The windows include five vertical wood divided-light casement windows flanked by (full-height) arched shutters on the eastern portion of the façade and a pair of vertical wood divided-light casement windows within a common wood frame on the western portion of the façade. The eight paneled door, recessed within the entry porch with segmental arch opening, is constructed of wood and features a rectangular light with grille work. Character-defining detail include slightly arched entry porch opening supported by brick pillar, decorative wood shutters, and a brick chimney. Landscaped includes a lawn, flagstone paved area with a planter, and brick planter with small ficus trees. Alterations include the addition of maid's quarters at the rear in 1946. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
8/31/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1941
City of Glendale Building Permit Records

*P7. Owner and Address:
KARL E II & SALLY KNISELEY TR
913 MATILIJA RD
GLENDALÉ CA 91202-1034

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1001 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1001 Matilija Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-036

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1926. It is rectangular in plan with a low-pitched hipped and gabled roof and flat roof with parapet to the rear clad in clay tile. The primary façade is asymmetrical. The walls are clad in textured smooth stucco. The windows include divided-light casement and fixed pane constructed of wood and aluminum. Character-defining features include exposed rafter tails and overhanging second story with wood brackets, simple turret on second story adjacent to the main entry featuring weathervane, decorative vents on the east elevation, recessed windows, and decorative iron work. Alterations include enclosing of a second story balcony in 1950. Landscape includes terra cotta colored cement stairs and curved walkway to raised porch entry and lawn sloping down to sidewalk. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1926
Los Angeles County Assessor

*P7. Owner and Address:
PEEBLES BYRON CO TR
1001 MATILIJIA RD
GLENDALE CA 91202-1035

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

**State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD**

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1007 Matilija Rd.

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1007 Matilija Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-037

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1926. It is L-shaped in plan with a low-pitch multiple gable roof, clad in clay tile. The primary façade is asymmetrical. The walls are clad in rough stucco. The windows are slightly recessed and include casement divide-lights and a center fixed picture window flanked by fixed divided-lights all constructed of wood. Character-defining features include exterior courtyard enclosed with a half height wall and patio roof supported by wood posts at the main entry featuring a wrought iron gate and concrete porch and decorative iron grille work balustrades around windows. Landscaping consists of a Jacaranda tree set in lawn, succulents, hibiscus, leafy plants in beds surrounding house exterior walls, with concrete stairs, and walkway to front porch. Alterations include the addition of a detached garage with guest house constructed in 1928, and a wood trellis at the front porch. The overall integrity of this building is good.

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

***P6. Date Constructed/Age and Source:** Historic Prehistoric
 Both

1926
Los Angeles County Assessor

***P7. Owner and Address:**
MARY E MCVAY TR
1007 MATILIJIA RD
GLENDALE CA 91202-1035

***P8. Recorded by:** (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

***P9. Date Recorded:** _____
8/8/2011

***P10. Survey Type:** (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

***P11. Report Citation:** (Cite survey report and other sources, or enter "none.") None

***Attachments:** NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1011 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 1011 Matilija Rd. _____ City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
 Los Angeles County Assessor's Parcel Number: 5630-005-031

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence constructed in the Ranch style, constructed in 1964. It is L-shaped in plan with a low-pitch gable roof, clad in asphalt singles. The primary façade is asymmetrical. The walls are clad in horizontal wood-lap above with smooth stucco below, and open car port supported by square brick piers. The windows include aluminum sliding windows. The paneled door features decorative glass panel. Character-defining features include detailed perforated screen block on the attached carport, recessed front entry porch, and moderate eave over hang and plain fascia board. Landscaping consists of mature multi-trunk fir trees, row of conical cypress and a magnolia tree. The overall integrity of this building is good to excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1964
Los Angeles County Assessor

*P7. Owner and Address:
AGHDAS JADIDI
1011 MATILIJA RD
GLENDALE CA 91202-1035

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1012 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M.

c. Address 1012 Matilija Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-006

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Mediterranean Revival style, constructed in 1924. It is rectangular in plan with a multiple hip roof, clad in asphalt shingles. The walls are clad in smooth stucco. The primary façade is asymmetrical, composed of one central block with two symmetric hipped roofs capping the front facade. The windows are primarily casement style, with some double-hung divided-lights, all constructed of wood. Character-defining features are extensive second story, projecting entry porch with arched openings with low-pitched hipped roof, decorative wrought iron, and brick chimney in interior of dwelling. Alterations include addition of roof over second story balconies in circa 1945. Landscaping consists of mature palm in rear of property and front property line. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____

7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1924

City of Glendale Building Permit Records

*P7. Owner and Address:

VAGRAM & GOAR TOPADZHIKYAN

1012 MATILIJA RD

GLENDALE CA 91202-1036

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

6/2/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1018 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1018 Matilija Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-005

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1940. It is rectangular in plan with a cross-gable roof, clad in asphalt shingles. The walls are clad in wood-lap with accents of brick on lower portion of façade. The primary façade is asymmetrical. The windows are primarily double-hung divided-lights with large, diamond-patterned mullions in upper sash, constructed of wood; the door is situated perpendicular to the street, housed in the protruding front gabled wing beneath a shed roof. Character-defining features are red brick chimney situated in the center of the house, top sash of double-hung windows decorated with large diamond-paned mullions, wooden shutters flanking windows, and bay window with similar diamond-paned mullions. Alterations include replacement of wood shingles with asphalt shingle roofing in 1963, side addition to cross gabled central block with lower roofline in 1992, and addition of a fence in 1998. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1940
City of Glendale Building Permit Records

*P7. Owner and Address:
VATCHE & TALIN KOUYOUMDJIAN
1018 MATILIJIA RD
GLENDALE CA 91202-1036

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/2/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1021 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1021 Matilija Rd. _____ City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-032

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Mediterranean Revival style with Italianate influences, constructed in 1921. It is L-shaped in plan with a low-pitched hip roof, clad in clay tile. The primary façade is asymmetrical. The walls are clad in smooth stucco. Windows are fixed and casement type divided-light and include heavy window surrounds. The arched main entry features molded archivolts accented by rope twist attenuated columns, and a small white canvas half-domed awning. The door features a vertical glazed entry with glazed vertical sidelights and architrave trim. Character-defining details include molded string course between first and second level on western portion of façade, decorative shutters, Beaux-arts frieze detailing over portico with quatrefoil medallion window, and exposed rafter tails. Alterations include an addition in 1922. The door and or window positions were modified in 1939. The rear patio was enclosed in 1942. Landscaping consists of a low retaining wall and wrought iron fence with concrete columns finished in smooth stucco, mature trees, lawn, rose bushes and mature hedges. The overall integrity of this building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1921
Los Angeles County Assessor

*P7. Owner and Address:
VICTORIA L WALLS
1021 MATILIJIA RD
GLENDALE CA 91202-1035

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1022 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1022 Matilija Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5629-001-004

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Mediterranean Revival style, constructed in 1927. It is L-shaped in plan with flat roof with parapet with pitched roof on portion of primary elevation, all clad in clay tile. The walls are clad in rough stucco. The primary façade is asymmetrical. The windows are primarily steel framed casements, divided-light, with a few fixed, single pane picture windows, constructed of wood. Character-defining features are entryway defined by projecting entry porch with arched opening and balcony, inset porch on the eastern portion of the facade, exposed rafters, half height wall enclosing front patio, balcony above main entry, tripartite arched wood picture window on front facing wing, decorative vents, and stained glass. Alterations include addition of roof to second story balcony in 2002, enclosure of balcony on eastern elevation in 1972, addition of second story rectilinear picture window, and a reconfiguration of the roof on the front wing. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1927

Los Angeles County Assessor

*P7. Owner and Address:

JAMES E & RACHEL L GARRISON

1022 MATILIJIA RD

GLENDALE CA 91202-1036

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

6/6/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1027 Matilija Rd.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1027 Matilija Rd. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-005-035

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one and a half story single-family residence designed in the English Tudor Revival style, constructed in 1939. It is irregular in plan with a steeply-pitched hip and gable roof, clad in asphalt shingles. The primary façade is asymmetrical. The walls are clad with smooth stucco accented with rough cut irregular stone and horizontal wood-lap. The windows are diamond-pane fixed and casement and feature a large bay window on the front facing gable end. The main entry features a covered porch on the western portion of the front facing gable end supported by two rough stone posts. Entry door is six-panel wood with two diamond-pane lights. A Porte Cochere extends from the roof on the western portion of the façade and features a decorated iron gate. Character-defining features include a diamond detailed vent with shutters on the front facing gable end, Porte Cochere, tall brick chimney featuring natural brick trim and short chimney pot, and decorative wood shutters. Landscaping consists of low rusticated stone retaining wall at sidewalk, rose bushes, curved walkway to entry lined with low annual flowers, lawn, and mature tree. The overall integrity of this building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/8/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1939
City of Glendale Building Permit Records

*P7. Owner and Address:
EVA WEBBER
1027 MATILIJIA RD
GLENDALE CA 91202-1035

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1000 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 1000 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-013

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence, on a corner lot, designed in the Spanish Colonial Revival style, constructed in 1931. It is U-shaped in plan with multiple gable and shed roofs clad in clay tile. The walls are clad in textured stucco. The primary façade is asymmetrical. The windows are wood divided-light casement, some with wrought iron grille work. The door appears to be constructed of wood. Character-defining features include the multi-gabled clay tile roof, decorative wrought iron, decorative vents, wrought iron balconies, tile door surround, and stucco exterior chimney. Alterations include new garage with modern looking doors. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1931
City of Glendale Building Permit Records

*P7. Owner and Address:
DOLORES M FRIEDMAN
1000 W MOUNTAIN ST
GLENDALE CA 91202-1042

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1001 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1001 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-003-031

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1945. It is rectangular in plan with a lo-pitch hip roof, clad in asphalt shingles. The walls are clad in wood-lap and smooth stucco with accents of brick (under the three paned windows). The façade is asymmetrical. The two-stall garage features a flat roof with hipped hood. The windows are primarily casement constructed of metal; the door is multi-paneled constructed of wood. Character-defining features are curved brick stairway, low-pitch roof, stuccoed and wood wall cladding, metal windows, and door recessed within inset entry porch with metal post. Alterations include the addition of a garden window. Landscaping consists of sloping groundcover and shrubbery and mature trees on the west side of the house. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1945
City of Glendale Building Permit Records

*P7. Owner and Address:
ED AZIZ
1001 W MOUNTAIN ST
GLENDALE CA 91202-1041

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1011 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 1011 W. Mountain St. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
 Los Angeles County Assessor's Parcel Number: 5630-003-027

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Modern style, constructed in 1948. It is rectangular in plan with a low-pitched shed roof. The façade is asymmetrical. The walls are clad in with stucco. The windows consist of wood divided-light with three tall panes and three smaller panes above (on the east corner of the house), metal sliding window, and large tripartite windows in the center of the house that is constructed of wood; the door is multi-paneled wood. A wrought-iron security bar covers the east-facing window adjacent to chimney. The character-defining features of the house are the sharply angled roof and wide primary façade. Landscaping consists of a row of cypress trees and other vegetation in front of the house, a low retaining wall, and sloping ivy and other shrubbery. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1948
City of Glendale Building Permit Records

*P7. Owner and Address:
RANDALL W NICKLAUS
1011 W MOUNTAIN ST
GLENDALE CA 91202-1041

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1014 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1014 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-004-017

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed with elements of Minimal Traditional and Ranch styles, constructed in 1938. It is rectangular in plan with a low-pitch cross-gable roof, clad in composition shingle. The walls are clad in stucco with wood trim. The primary façade is asymmetrical. The windows are divided-light casement made of wood. Character-defining features are fixed decorative shutters, front and side gables, brick chimney, and wide recessed porch with wood support posts. Alterations include reroof and the addition of a bedroom and new door. Landscaping consists of a curved brick walkway and planters. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1938
City of Glendale Building Permit Records

*P7. Owner and Address:
MARJORIE N & JOHN L JR SADD ETAL
1014 W MOUNTAIN ST
GLENDALE CA 91202-1042

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
8/8/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1017 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 1017 W. Mountain St. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-003-028

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Modern style, constructed in 1951. It is rectangular in plan with a flat roof, clad in rolled asphalt. The walls are clad in brick and board-and-batten. The front entrance features an exterior courtyard enclosed with a concrete block wall capped with brick. The windows are floor to ceiling separated by aluminum framing. Character-defining features are wide primary façade, flat roof, fascia and a brick chimney, and small concrete platform steps along the driveway leading to the side of the house. Landscaping consists of a low retaining wall with sloping ivy and mature trees at the east and west ends of the house. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric Both
1951
City of Glendale Building Permit Records

*P7. Owner and Address:
ALPHEUS & ELIZABETH ROREX TR
1017 W MOUNTAIN ST
GLENDALE CA 91202-1041

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1021 W. Mountain St.

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 1021 W. Mountain St. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
 Los Angeles County Assessor's Parcel Number: 5630-003-029

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the American Colonial Revival style, constructed in 1941. It is rectangular in plan with a low-pitch gable roof, clad in asphalt shingles. The walls are clad in stucco on the lower story and wood-lap on the upper story. The façade is asymmetrical. The windows are double-hung and fixed divided-light constructed of wood with decorative wood shutters; the door is paneled wood with sidelights. Character-defining features are decorative wood shutters, a curved brick staircase, entry portico, projecting wing with shed roof, clad in asphalt shingles, and a two-stall garage on the first level. Alterations include contemporary garage door with lights and light fixture under eave. Landscaping consists of a low retaining wall, steeply sloped landscaping and shrubbery, and one large magnolia tree on the east side of the house. The overall integrity of the building is excellent.

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

***P6. Date Constructed/Age and Source:** Historic Prehistoric
 Both

1941
City of Glendale Building Permit Records

***P7. Owner and Address:**
JOHN V & HEATHER LIPARI
1021 W MOUNTAIN ST
GLENDALE CA 91202-1041

***P8. Recorded by:** (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

***P9. Date Recorded:** 6/14/2011

***P10. Survey Type:** (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

***P11. Report Citation:** (Cite survey report and other sources, or enter "none.") None

***Attachments:** NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1025 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1025 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-003-026

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the American Colonial Revival style, constructed in 1936. It is rectangular in plan with a low-pitch hip roof, clad in asphalt shingles. The walls are clad in wood clapboard. The façade is asymmetrical. The house has divided-light casement windows, constructed of wood; the door is made of wood panels with sidelights and a glass fanlight transom panel divided by spokes. Character-defining features are a curved driveway to the entrance, decorative shutters on the windows, two-story portico spanning the full width of the façade with five full-height classical columns, a small balcony on the second floor and a Porte Cochere. Alterations include two bedrooms added, one in 1959 and the other in 1963, on the second story. Another small addition was made at the rear of the house in 2007. Landscaping consists of sloping lawn with retaining wall, mature trees in front of the house, and shrubbery. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1936

City of Glendale Building Permit Records

*P7. Owner and Address:

CARL C & DORIS A EYERICK TR

1025 W MOUNTAIN ST

GLENDALE CA 91202-1041

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

6/14/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1039 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of 1/4 of Sec _____ ; B.M. _____

c. Address 1039 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-003-025

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1925. It is rectangular in plan with a multiple-gabled roof, clad in clay tile. The walls are faced with stucco. The façade is asymmetrical. The windows are primarily fixed divided-light, constructed of wood, with one large picture window. Character-defining features are arched openings, projecting porch with cross-gable roof, Porte Cochere with side gable clad in clay tile, attached two-stall garage with side gable clad in clay tile, a small rectangular porch with wrought iron railings, a widow's walk on the roof, and a chimney with three flues. Alterations include the removal of decorative window shutters. Landscaping consists of a sloped lawn, a low retaining wall along the driveway, a mature magnolia tree on the west side of the house, and a few palm trees in front of the house. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1925

Los Angeles County Assessor

*P7. Owner and Address:

ROBERT P & KERRY A MULDER

1039 W MOUNTAIN ST

GLENDALE CA 91202-1041

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division

633 E. Broadway, Rm. 103

Glendale, CA 91206

*P9. Date Recorded: _____

6/14/2011

*P10. Survey Type: (Describe)

N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1045 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 1045 W. Mountain St. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-003-024

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one and a half story single-family residence designed in the French Eclectic style, with English Tudor Revival influence, constructed in 1950. It is L-shaped in plan with a multiple-gabled, steeply-pitched roof, and a hipped gambrel (on one wing of the house), clad in wood shingles. The walls are clad in with stucco with accents of wood-lap. The façade is asymmetrical. The windows are primarily divided-light casement and fixed constructed of wood. Character-defining features are half timbering on the attached garage, decorative wood shutters, and a brick chimney. Alterations include reroof replacing wood shake with composition shingle. Landscaping consists of lavender, roses and other shrubbery on the west side, sloping ivy and a mature tree in front of the house. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1950
City of Glendale Building Permit Records

*P7. Owner and Address:
KENNETH J&DEBORAH A BROWN
1045 W MOUNTAIN ST
GLENDALE CA 91202-1041

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 1051 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 1051 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-003-023

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1932. It is irregular in plan with a low-pitch multiple gable and hip roofs, clad in clay tile. The walls are clad in stucco. The façade is asymmetrical. The windows are primarily divided-light casement with decorative shutters, and there is also one large picture window with an arched top, and one square picture window with multi-paneled sidelights; all the windows are constructed of wood. Character-defining features are a rectangular porch with arched openings, a recessed window opening for the picture window, wing wall on west side of the house, inset second-story balcony with wood balustrade, Porte Cochere with hipped roof and arched opening, and decorative vents. Alterations include a possible replacement of the original brick chimney with a stucco chimney in 1994. Landscaping consists of a long sloping lawn, one mature tree is on the west side of the house, and one mature palm tree by the driveway on the east side of the house, and concrete driveway on the east side of the house. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1932
City of Glendale Building Permit Records

*P7. Owner and Address:
GLENN R & POMM HEPNER
1051 W MOUNTAIN ST
GLENDAL CA 91202-1041

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 877 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; _____ B.M.

c. Address 877 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-007-033

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Spanish Colonial Revival style, constructed in 1930. It is rectangular in plan and has a side gable roof clad with clay tile and features a projecting wing with front facing gable on the eastern portion of the façade and exposed rafter tails. The walls are clad in rough stucco. The façade is asymmetrical. The windows are casement, divided-light, constructed of wood and steel; the door is non-original with panels and rectangular light and constructed of wood. Character-defining features include a round arch surrounding the recessed main entry, exposed rafter tails and decorative iron work, decorative light fixtures on both sides of the arched entry, divided-light French doors with wrought-iron balustrades, and second story overhang above the first story French door. Alterations include a non-original front door; the porch was added in 1938. Landscaping consists of a sloping lawn with a curved stepped stone/slate walkway leading to the main entry; mature trees frame the house on either side. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1930
City of Glendale Building Permit Records

*P7. Owner and Address:
BEALA B & CRISTINA M NEEL
877 W MOUNTAIN ST
GLENDALE CA 91202-1047

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 879 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 879 W. Mountain St. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-007-032

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in the Neo-Mediterranean Revival style, constructed in 1987. It is square in plan with a flat roof and plain boxed cornice. The walls are clad in rough stucco. The façade is symmetrical. The windows are primarily divided-light and include one floor length Palladian and sliding windows with faux muntins on the second story above the main door; the windows on the first story also have semicircular tops; all windows are constructed of vinyl. The double door features two panels on each door and is constructed of wood; above the door is a plain shelf. Character-defining features are a two-story portico with pair of classical columns, ionic pilasters decorating both the first and second story, and a frieze that separates the first and second story. Landscaping consists of sloping juniper along the staircase, groundcover sloping upwards towards the house, and palm trees around the house; a concrete curved staircase leads to the front entrance.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1987
Los Angeles County Assessor

*P7. Owner and Address:
SHELLIE GILMORE
2973 HARBOR BLVD
COSTA MESA CA 92626

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

**State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD**

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 900 W. Mountain St.

P1. Other Identifier: _____

***P2. Location:** Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 900 W. Mountain St. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
 Los Angeles County Assessor's Parcel Number: 5630-006-030

***P3a. Description:** (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed with elements of the American Colonial Revival and Spanish Colonial Revival styles, constructed in 1934. It is rectangular in plan with a low-pitch cross-gable roof, clad in modified bitumen. The walls are clad in smooth stucco with accents of wood-lap in the gable ends. The primary façade is asymmetrical. The windows are divided-light casement and fixed, constructed of wood. Character-defining features include inset second story balcony with wood posts and balustrade, recessed entry porch with wood posts, and divided-light picture windows. Alterations include backyard addition and removal of fixed wood shutters from all windows. The overall integrity of the building is good.

***P3b. Resource Attributes:** (List attributes and codes) HP2. Single family property

***P4. Resources Present:** Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

***P6. Date Constructed/Age and Source:** Historic Prehistoric
 Both

1934
City of Glendale Building Permit Records

***P7. Owner and Address:**
MICHAEL A MCCUSKER
900 W MOUNTAIN ST
GLENDALE CA 91202-1040

***P8. Recorded by:** (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

***P9. Date Recorded:** 8/5/2011

***P10. Survey Type:** (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

***P11. Report Citation:** (Cite survey report and other sources, or enter "none.") None

***Attachments:** NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 901 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 901 W. Mountain St. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-006-037

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1940. It is rectangular in plan with a multiple gable and hip roof, clad in asphalt shingles. The walls are clad in smooth stucco with plain wood shingle accents in gable ends. The façade is asymmetrical. The windows are divided-light double-hung and fixed constructed of wood; the multiple panel door with fanlight is constructed of wood. Character-defining features include columns at the entryway, a brick chimney, and decorative wood shutters. Landscaping consists of an ivy covered slope and mature trees, a central stairway with a metal railing leads to the main entry. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1940
City of Glendale Building Permit Records

*P7. Owner and Address:
DUANE A & GINA LADINE
901 W MOUNTAIN ST
GLENDALE CA 91202-1039

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 909 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 909 W. Mountain St. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-006-036

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Ranch style, constructed in 1950. It is L-shaped in plan with a low-pitch hip roof with exposed rafters clad in asphalt shingles. The walls are clad in rough stucco with slate accents by the main entry. The façade is asymmetrical. The windows are non-original vinyl sliding with faux mullions; the door is wood with multiple panels and features a fanlight and sidelights. Character-defining features are decorative wood shutters and metal railing along the stairway leading to the main entry. Alterations include a non-original door and non-original vinyl windows; building permits show changes in roof cladding, enclosure of patio, and construction of the garage. Landscaping consists of steep ivy slope, a palm tree and cypress trees on the eastern portion of the property. The overall integrity of the building is fair.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1950
City of Glendale Building Permit Records

*P7. Owner and Address:
ANDRE BONYADIAN
909 W MOUNTAIN ST
GLENDALE CA 91202-1039

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 910 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 910 W. Mountain St. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-006-034

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Ranch style, constructed in 1935. It is rectangular in plan with a low-pitch side-gable roof, clad in asphalt shingles. The walls are clad in smooth stucco with accents of wood and brick veneer. The primary façade is asymmetrical. The windows are divided-light casement constructed of metal. Character-defining features include wood shutters, inset porch with decorative metal porch supports, decorative brick chimney, exposed rafter tails, wrought iron railings, and horizontal wood-lap siding. Landscaping consists of a brick wall with brick piers and wood balustrade and mature trees. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1935
City of Glendale Building Permit Records

*P7. Owner and Address:
BRENT L & ROSLYN T RICHARDS
910 W MOUNTAIN ST
GLENDALE CA 91202-1040

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 918 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 918 W. Mountain St. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-006-033

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed with elements of the English Tudor Revival style, constructed in 1940. It is L-shaped in plan with a steeply-pitched gable-on-hip roof with prominent front-facing gable, clad in asphalt shingles. The walls are clad in smooth stucco with accents of wood half-timbering, wood-lap, and flagstone. The primary façade is asymmetrical. The windows are divided-light casement constructed of steel. The front door is recessed within entry porch and includes sidelights. Character-defining features include half timbering, fixed shutters, integrated two-car garage, and projecting three-sided bay window. Landscaping consists of winding brick walkway, lawn, low brick planter, and several mature hedges. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/6/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1940
City of Glendale Building Permit Records

*P7. Owner and Address:
PATRICK M & CECELIA ANDERSON
918 W MOUNTAIN ST
GLENDALE CA 91202-1040

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 8/5/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 921 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 921 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-006-035

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1940. It is rectangular in plan with a hip roof, clad in asphalt shingles. The walls are clad in rough stucco with accents of wood-lap and a brick veneer on the western portion of the façade. The façade is asymmetrical. The windows are primarily double-hung divided-light constructed of wood, including one projecting picture window. The door is constructed of wood. Character-defining features are wide inset porch with metal railing and wood posts, and decorative wood shutters. Alterations include an addition at the rear of the residence and three z-bar vinyl sliders with internal muntins at right front façade. Landscaping consists of upward sloping ivy groundcover and mature trees framing the house on either side that include cypress trees to the east and a shade tree to the west. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1940
City of Glendale Building Permit Records

*P7. Owner and Address:
ROUBEN KHODADIAN
921 W MOUNTAIN ST
GLENDALE CA 91202-1039

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 6L

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 929 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 929 W. Mountain St. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-003-035

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the Minimal Traditional style, constructed in 1941. A significant addition was made to the house in 2009, adding a large second story and additional square footage at the ground floor. The original style has been altered, though the original form of the one-story house is still visible. The overall integrity of the building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1941
City of Glendale Building Permit Records

*P7. Owner and Address:
JOSE R & LESLIE G REYES
929 W MOUNTAIN ST
GLENDALE CA 91202-1045

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 6L

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 934 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
 *b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
 c. Address 934 W. Mountain St. City Glendale Zip 91202
 d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
 e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-005-025

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a one-story single-family residence designed in the French Eclectic style, constructed in 1941. It is irregular in plan with steeply-pitched side-gable roof with prominent front-facing gable, clad in asphalt shingles. The primary façade is asymmetrical. The walls are clad with smooth stucco with brick accents and wood-lap in gable ends. The windows are primary double-hung divided-light and include a three-sided bay window and two large picture windows on the primary façade. All windows are constructed of new dark brown aluminum. Character-defining features are brick chimney, wood-lap and half timbering in front facing gable ends, steeply pitch roof, and arch brick surround above main entry. Alterations include large addition on northerly elevation in 2004. Landscaping consists of small strip of lawn. The overall integrity of this building is poor.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
5/27/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1941
City of Glendale Building Permit Records

*P7. Owner and Address:
RODNEY G NEITZEL TR
934 W MOUNTAIN ST
GLENDALE CA 91202-1046

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 2/10/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 935 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)
*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____
c. Address 935 W. Mountain St. City Glendale Zip 91202
d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN
e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)
Los Angeles County Assessor's Parcel Number: 5630-003-034

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a two-story single-family residence designed in a American Colonial Revival style with barn-like elements, constructed in 1949. It is rectangular in plan with a gambrel roof, clad in asphalt shingles; the second story with shed roof has eaves projecting with exposed rafter tails. The walls are clad in cement blocks on the first floor and wood vertical board and batten on the second floor. The facade is asymmetrical. The windows are double-hung constructed of wood; the door is wood with eight divided-lights and a mail slot. Character-defining features are wood swinging garage doors, shed dormer that extends the majority of the second story, and a flat hood above the main entry. Landscaping consists of groundcover on the west side of the house and fescue grass by the low wood fence on the east side of the house; mature shade trees are on either side of the house. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #)
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1949
City of Glendale Building Permit Records

*P7. Owner and Address:
NANCY D MOURE TR
935 W MOUNTAIN ST
GLENDALE CA 91202-1045

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: 6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
HRI # _____
Trinomial _____
NRHP Status Code 5D3

Other Listings _____
Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 939 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 939 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-003-033

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family residence (with the garage on the first level) designed in the Minimal Traditional style with Ranch elements, constructed in 1952. It is rectangular in plan with a cross-gable roof, clad in asphalt shingles. The garage at the first level extends beyond the façade of the residence and is covered by a shed roof. The walls are clad with rough stucco with wood-lap accents under the eave of the front facing gable. The facade is asymmetrical. Fenestration consists of aluminum sliders and picture window flanked by two casement windows; the door is wood with a glass square in the upper center. Character-defining features include a small porch with decorative metal columns, garage on the first level, and a chimney. Alterations include aluminum sliders with foam surrounds, new sconce at entry, new paneled entry door, foam molding around garage door, foam molding around fixed windows, new garage door, and removal of the front planter. Landscaping consists of sloped ivy and lantana with a retaining wall and curved concrete stairs to the entrance. The overall integrity of the building is good.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1952
Los Angeles County Assessor

*P7. Owner and Address:
ARTYOM SIMONYAN
939 W MOUNTAIN ST
GLENDALE CA 91202-1045

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____

State of California The Resources Agency
 DEPARTMENT OF PARKS AND RECREATION
PRIMARY RECORD

Primary # _____
 HRI # _____
 Trinomial _____
 NRHP Status Code 5D3

Other Listings _____
 Review Code _____ Reviewer _____ Date _____

Page 1 of 1 *Resource Name or # (Assigned by recorder) 945 W. Mountain St.

P1. Other Identifier: _____

*P2. Location: Not for Publication Unrestricted

*a. County Los Angeles and _____ (P2c, P2e, and P2b or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad Burbank Date 1972 T _____ ; R _____ ; 1/4 of _____ 1/4 of Sec _____ ; B.M. _____

c. Address 945 W. Mountain St. City Glendale Zip 91202

d. UTM: (Give more than one for large and/or linear resources) Zone _____, _____ mE/ _____ mN

e. Other Locational Data: (e.g., parcel #, directions to resource, etc., as appropriate)

Los Angeles County Assessor's Parcel Number: 5630-003-032

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

This is a single-family residence (with the garage on the first level) designed in the Ranch style, constructed in 1948. It is rectangular in plan with a hip roof, clad in asphalt shingles. The walls are clad in vertical wood (smooth, flush boards) with accents of wood shingle and smooth stucco and stone veneer exterior steps and chimney. The façade is asymmetrical. The house has divided-light double-hung sash windows constructed of wood, and one projecting, multi-paned picture window; the door has lower wood panels in an "X" shape with multi-paned glass above. Character-defining features are a porch with wood support post with diagonal braces, slate chimney, and slate staircase with decorative metal balustrades on porch and steps. Alterations include aluminum garage door with lights and sconce installed above. Landscaping consists of a retaining wall with sloping groundcover, and a slate staircase to front entrance. The overall integrity of the building is excellent.

*P3b. Resource Attributes: (List attributes and codes) HP2. Single family property

*P4. Resources Present: Building Structure Object Site District Element of District Other (Isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects.)



P5b. Description of Photo: (view, date, accession #) _____
7/5/2011

*P6. Date Constructed/Age and Source: Historic Prehistoric
 Both

1948
City of Glendale Building Permit Records

*P7. Owner and Address:
ROBERTS WILLIAM N JR CO TR
945 W MOUNTAIN ST
GLENDALE CA 91202-1045

*P8. Recorded by: (Name, affiliation, and address) Glendale Planning Division
633 E. Broadway, Rm. 103
Glendale, CA 91206

*P9. Date Recorded: _____
6/14/2011

*P10. Survey Type: (Describe)
N. Cumberland Heights Reconnaissance Survey (Update of 2004 Survey)

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") None

*Attachments: NONE Location Map Sketch Map Continuation Sheet Building, Structure, and Object Record
 Archaeological Record District Record Linear Feature Record Milling Station Record Rock Art Record
 Artifact Record Photograph Record Other (List): _____